

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
GREAT AMERICAN INSURANCE COMPANY			Ref:	Ref : CS/GAI20012988/Uvf3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date :	07-12-2020		
			Code :	-		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	YP 4000T		spected	SJP 9098G	
	Policy No.		Covera	<u> </u>	0.00	
	Claim No.	CLMOMVC000003924	Exces	<u> </u>	0.00	
	Assign From	ELIZBETH CHEW	Assigr	n Date	25/11/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI AVANTE (A)	c.c		1591	
	Engine No.	HIDDEN	Year o	f Reg.	2009	
	Chassis No.	KMHDU41BR9U728249	Colour	•	BLACK	
	Odometer	144466	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/60 R15	LING LO	ONG	6 mm	
	L/H Front Tyre	195/60 R15	LING LO	ONG	6 mm	
	R/H Rear Tyre	195/60 R15	MEMBA	AT	6 mm	
	L/H Rear Tyre	195/60 R15	MEMBA	AT	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	23/11/2020	Inspec	tion Date	25/11/2020	
	Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD				
		3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					