

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS20012992/KVF3E2
Date: 04/01/2021

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SKD5218E Insured Vehicle No : SJM4525P
Date of Loss: 23/11/2020 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD5218E
Make & Model: TOYOTA HARRIER, 2.4 240G (ACU30) (A) Engine No: 2AZB285917
Reg. Date: 09/10/2007 (Man. Year: 2007) Chassis No: ACU300075997
Colour: Black Odometer: 323830 km
Engine Capacity: 2362 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R20 Rear Tyre Size: 245/45Z R20
Front Left Side: Falken 9 mm Rear Left Side: Falken 9 mm
Front Right Side: Falken 9 mm Rear Right Side: Falken 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,009.50	1,019.50	-10.00	-0.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	420.00	280.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,709.50	1,439.50	270.00	15.79
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	1,709.50	1,150.00	559.50	32.73
+ GST 7.00/7.00% (S\$)	119.67	80.50	39.17	32.73
Nett Amount (S\$)	1,829.17	1,230.50	598.67	32.73

INSPECTION

Date of Assignment: 24/11/2020 Present Location: Alan's United Auto Pte Ltd (HQ)
Date Inspected: 09/12/2020 Inspected At: Alan's United Auto Pte Ltd (HQ)
Estimated Period of Repair: 2.0 days Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2021)
Parts:	M1-SUV	TOYOTA HARRIER 2.4 240G (ACU30) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD5218E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA (WCP)	Bent	360.00 F	*360.00 F
2	1		*REAR BUMPER REINFORCEMENT (WCP)	Bent	180.00 F	*280.00 F
3	1		*REAR BUMPER SPONGE (WCP)	Distorted / Cracked	105.00 F	*105.00 F
4	1		*REAR BUMPER REVERSE SENSOR (1 SET)	Shorted	300.00 FS	*200.00 FS
					Sub Total (\$\$)	945.00 945.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	64.50 74.50
					Total Parts (\$\$)	1,009.50 1,019.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY REPLACED PARTS	New	400.00	220.00
2	TO REMOVE DAMAGED PARTS,PANEL BEATING,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	300.00	200.00
Gross Labour Cost (\$\$)			700.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >