

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJM4525P
Accident Date : 23-Nov-2020

Our Ref : 020164 (ECICS) / CHAN

SYED FADZLEIGH BIN SHAFARI
BLK 803 WOODLANDS STREET 81
#06-57
Singapore 730803

No. : 06287

Date : 24-Nov-2020

PAGE : 1

Not Authorised
61 Rm @ 1150/hr
Putty After Pain
2 days

ESTIMATED COST OF REPAIR FOR TOYOTA HARRIER 2.4A SKD5218E

1 pc Rear bumper fascia
1 pc Rear bumper reinforcement
1 pc Rear bumper sponge

A1 360.00 —
A2 280.00 —
dis/cm 105.00 —

745.00

Add: 10% : 74.50

1 pc Rear bumper reverse sensor

shen 819.50 *200sn*
300.00 sn

To putty and spray replaced parts

400.00 *220cl*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

300.00 *200cl*

Total : S\$ 1,819.50

Singapore Dollars One Thousand Eight Hundred
and Nineteen and Cents Fifty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: