

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012994/R1CF3Q2

Date: 05/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00022232001
Claimant Vehicle No :	SKZ4733A	Insured Vehicle No :	YJ9044R
Date of Loss:	23/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204555/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ4733A	Engine No:	L13Z11015532
Make & Model:	HONDA JAZZ, 1.3 (A)	Chassis No:	JHMG68509S215451
Reg. Date:	02/07/2009 (Man. Year: 2008)	Odometer:	152052 km
Colour:	Grey		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R14	Rear Tyre Size:	185/65R14
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,331.60	8,083.76	247.84	2.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	3,350.00	690.00	17.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,371.60	11,433.76	937.84	7.58
Approved Total (Overridden) (\$\$)		9,100.00		
(\$\$)	12,371.60	9,100.00	3,271.60	26.44
+ GST 7.00/7.00% (\$\$)	866.01	637.00	229.01	26.44
Nett Amount (\$\$)	13,237.61	9,737.00	3,500.61	26.44

INSPECTION

Date of Assignment:	25/11/2020	
Date Inspected:	25/11/2020 Inspected At:	15 FAN YONG ROAD Repairer: Mova Automotive Pte Ltd (Bukit Merah)
Estimated Period of Repair:	16.0 days	

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2021)
Parts:	144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ4733A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SPORT RIM LH	Scratched	682.40 FL	*682.40 FL
2	1		*FRONT KNUCKLE ARM LH	Bent	254.50 FL	*254.50 FL
3	1		*FRONT KNUCKLE HUB LH	Bent	163.90 FL	*163.90 FL
4	1		*FRONT KNUCKLE BEARING LH	Necessary	123.30 FL	*123.30 FL
5	1		*FRONT LOWER ARM LH	Bent	234.80 FL	*234.80 FL
6	1		*FRONT SHOCK ABSORBER LH	Bent	321.80 FL	*321.80 FL
7	1		*FRONT DOOR RH	Bent	859.90 FL	*859.90 FL
8	1		*FRONT DOOR STICKER RH	Necessary	18.50 FL	*18.50 FL
9	1		*FRONT DOOR OUTER HANDLE RH	Cut	84.80 FL	*84.80 FL
10	1		*FRONT DOOR LOCK RH	Jammed	239.60 FL	*239.60 FL
11	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	96.40 FL	*96.40 FL
12	1		*FRONT DOOR GLASS REGULATOR MOTOR RH	Cut	405.30 FL	*405.30 FL
13	1		*CENTER PILLAR RH	Bent	602.90 FL	*602.90 FL
14	1		*ROOF SIDE PANEL RH (NPA)	Repair	0.00 FL	*- FL
15	1		*REAR DOOR RH	Bent	724.50 FL	*724.50 FL
16	1		*REAR DOOR STICKER RH	Necessary	18.50 FL	*18.50 FL
17	1		*REAR DOOR HINGE TOP RH	Bent	36.40 FL	*36.40 FL
18	1		*REAR DOOR HINGE BOTTOM RH	Bent	38.40 FL	*38.40 FL
19	1		*REAR DOOR CHECKER RH	Bent	39.60 FL	*39.60 FL
20	1		*REAR DOOR WEATHERSTRIP RH	Necessary	103.90 FL	*103.90 FL
21	1		*REAR DOOR LOCK RH	Bent	215.00 FL	*215.00 FL
22	1		*REAR DOOR GLASS REGULATOR MOTOR RH	Bent	373.90 FL	*373.90 FL
23	1		*ROCKER PANEL RH	Bent	401.30 FL	*401.30 FL
24	1		*REAR FENDER RH	Buckled	675.90 FL	*675.90 FL
25	1		*REAR BUMPER	Deformed	520.40 FL	*520.40 FL
26	1		*REAR SPORT RIM LH	Cut	682.40 FL	*682.40 FL
27	1		*REAR SHOCK ABSORBER LH	Serviceable	189.80 FL	*- FL
28	1		*REAR WHEEL BEARING LH	Bent	240.60 FL	*240.60 FL
29	1		*REAR AXLE	Bent	1,221.30 FL	*1,221.30 FL
30	1		*REAR BRAKE CALIPER LH	Bent	394.50 FL	*394.50 FL
31	1		*FRONT TYRE LH (70%)	Cut	160.00 FS	*112.00 FS
32	1		*REAR QUARTER GLASS SEALANT RH	Necessary	40.00 FS	*40.00 FS
33	1		*REAR TYRE LH (70%)	Cut	160.00 FS	*112.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,324.50	10,038.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,992.90	1,954.94
Total Parts (\$\$)	8,331.60	8,083.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT/WELD REAR FENDER RH,CENTER PILLAR RH,ROCKER PANEL RH,KNOCK AND STRAIGHTEN ROOF PANEL RH,FRONT DOOR LH,REAR DOOR LH,REMOVE AND REPLACE ACCIDENT DAMAGED PARTS.REALIGN ALL CONNECTION	New	1,600.00	1,400.00
2	SPRAY PAINT FRONT DOORS RH & LH,CENTER PILLAR RH,ROCKER PANEL RH,ROOF PANEL,REAR DOORS RH & LH,REAR FENDER RH,REAR BUMPER	New	1,500.00	1,300.00
3	REMOVE & REINSTALL FRONT UNDERCARRIAGE SUSPENSION LH	New	150.00	100.00
4	REMOVE & REFIT FRONT DOOR MECHANISM AND CHECK LOCKING SYSTEM	New	50.00	50.00
5	REMOVE & REFIT REAR DOOR TRIM BOARD,MECHANISM AND CHECK LOCKING SYSTEM	New	50.00	50.00
6	REMOVE & REFIT FRONT AND REAR SEAT ASSY,FLOOR CARPET,SIDE GARNISH,INNER TRIM	New	150.00	80.00
7	REMOVE & REFIT REAR QUARTER GLASS RH	New	80.00	60.00
8	REMOVE & REINSTALL REAR SUSPENSION,REAR AXLE	New	250.00	150.00
9	COMPUTER WHEEL ALIGNMENT	New	60.00	60.00
10	RUST PROOF AFFECTED AREAS	New	150.00	100.00
Gross Labour Cost (\$\$)			4,040.00	3,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >