

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013000/KPA3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100495984

Claimant
Vehicle No : SMQ6499L **Insured Vehicle No :** SBH9893P

Date of Loss: 21/11/2020 Nature of Claim: TP Claim No: 0863426989SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ6499L		
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Engine No:	G4FGKU175392
Reg. Date:	28/11/2019 (Man. Year: 2019)	Chassis No:	KMHD841CMLU938325
Colour:	Metallic Grey	Odometer:	48283 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 4 mm	Rear Left Side:	Nexen 4 mm
Front Right Side:	Nexen 4 mm	Rear Right Side:	Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,490.40	2,044.44	445.96	17.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,165.00	815.00	41.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,470.40	3,209.44	1,260.96	28.21
+ GST 7.00/7.00% (S\$)	312.93	224.66	88.27	28.21
Nett Amount (S\$)	4,783.33	3,434.10	1,349.23	28.21
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,836.10		

INSPECTION

Date of Assignment: 24/11/2020

Date Inspected: 24/11/2020 Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,056.30 FL	*1,056.30 FL
2	1		*REAR BOOTLID AVANTE EMBLEM	Necessary	46.50 FL	*46.50 FL
3	1		*REAR BOOTLID LOGO EMBLEM	Necessary	180.30 FL	*54.70 FL
4	1		*REAR BUMPER	Buckled / Cracked	650.80 FL	*495.00 FL
5	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	39.60 FL	*- FL
6	1		*REAR BUMPER LOWER GARNISH COVER	Cracked	453.20 FL	*348.00 FL
7	1		*REAR BUMPER REFLECTOR COVER LH	Scratched	198.80 FL	*198.80 FL
8	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
11	1		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
12	1		*REAR NUMBER PLATE WITH HOLDER	Dented	50.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,015.50	2,484.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	525.10	439.86
Total Parts (\$\$)	2,490.40	2,044.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	800.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISING MATERIALS AT REAR BOOTLID ,REAR BUMPER ,REAR FENDER LH ,REAR END PANEL & ETC	New	1,000.00	600.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC TO EFFECT REPLACE OF REAR BUMPER	New	100.00	50.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	15.00
Gross Labour Cost (\$\$)			1,980.00	1,165.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >