



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 3636G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT	TO REPAIR SEE LABOUR	635.84	-
2	REAR BOOT HINGE	SERVICEABLE	134.20	-
1	REAR BOOT LOCK	SERVICEABLE	117.10	-
1	REAR BOOT STRICK	SERVICEABLE	68.40	-
1	REAR BOOT INSULATOR	SERVICEABLE	290.16	-
1	SET REAR BOOT INSULATOR CLIPS	NOT NECESSARY	38.00	-
1	REAR BOOT RUBBER	SERVICEABLE	217.58	-
1	REAR BOOT LOGO	NECESSARY	60.04	60.04
1	REAR BOOT 'VIOS'	NECESSARY	54.72	54.72
1	REAR BOOT 'E'	NECESSARY	54.72	54.72
1	REAR BOOT LOCK PANEL (ABOVE CAR PLATE)	SERVICEABLE	301.72	-
1	REAR BOOT OUTER LOCK	SERVICEABLE	152.36	-
1	REAR FENDER LH	SERVICEABLE	871.66	-
1	REAR FENDER RH	SERVICEABLE	871.66	-
1	REAR LAMP LH	SERVICEABLE	380.00	-
1	REAR LAMP RH	SERVICEABLE	380.00	-
1	REAR BUMPER	DEFORMED	533.48	533.48
2	REAR BUMPER SIDE RETAINER LH & RH	SERVICEABLE	196.00	-
1	REAR REINFORCEMENT	* CHECK	380.52	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	621.25	-
1	REAR END PANEL TOP GARNISH	* CHECK	218.40	-
1	SPARE TYRE TRUNK	SERVICEABLE	800.76	-
	LESS 25% DISCOUNT		-1,844.64	-175.74
			5,533.93	527.22
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR CAR PLATE NUMBER WITH HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	* CHECK	280.00	-
2	SET REAR FENDER SHIELD CLIPS (SN)	NOT NECESSARY	96.00	-

Report Ref No. CS/AGI20013005/R1qf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	52.10	30.00
			478.10	30.00
	<b>LABOUR</b>			
	SPRAY PAINTING TO ALL AFFECTED AREAS.		1,200.00	600.00
	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR BOOT AND REAR END PANEL		1,000.00	400.00
	CHECK WIRING SYSTEM & LIGHT.	NOT NECESSARY	100.00	-
	ANTI RUST TREATMENT.	NOT NECESSARY	120.00	-
	TO CHECK & ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIX REAR BOOT ATTACHMENT, MECHANISM & ASSY TO NEW BOOT.	NOT NECESSARY	200.00	-
	TO REMOVE / REFIX / REPLACE REVERSE SENSOR.		150.00	60.00
	TO REMOVE / REFIX INNER COMPARTMENT TO FACILITIES REPAIR.		150.00	60.00
	TO CHECK REAR BOOT WATER LEAKING.	NOT NECESSARY	200.00	-
	TO REMOVE / REFIX REAR EXHAUST BOX.	NOT NECESSARY	180.00	-
			3,400.00	1,120.00
<b>GRAND TOTAL</b>			<b>9,412.03</b>	<b>1,677.22</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$729.19 NETT)</b>				<b>1,677.22</b>

Report Ref No. CS/AGI20013005/R1qf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.