

## **LKK Auto Consultants Pte Ltd**

LKK Auto Consultants Pte L
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 2370D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	TO REPAIR SEE LABOUR	655.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	168.00	-
1	REAR BUMPER	DENTED	665.00	601.00
1	REAR BUMPER BEAM	BENT	145.00	145.00
1	REAR BUMPER SIDE RETAINER O/S	NOT NECESSARY	45.00	-
1	REAR BUMPER LOWER SKIRTING	DEFORMED / TORN	681.00	681.00
1	REAR END PANEL	DENTED	442.00	442.00
1	REAR END PANEL TOP GARNISH	SERVICEABLE	168.00	-
1	TAILLAMP O/S	SERVICEABLE	368.00	-
1	REAR FENDER INNER TRIM O/S	NOT NECESSARY	242.00	-
	LESS 10% DISCOUNT		-	-186.90
			3,579.00	1,682.10
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR FENDER INNER TRIM CLIPS O/S (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			430.00	230.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.		60.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID.		850.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	800.00
			2,360.00	1,580.00
	GRAND TOTAL		6,369.00	3,492.10

Report Ref No. CS/TP20013008/Utf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,650.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/TP20013008/Utf3e2

CHUA KANG SENG

**Licensed Appraiser**