

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013010/GQF3E2
Date: 24/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SMC2826B **Insured Vehicle No :** SLN3005B
Date of Loss: 13/11/2020 Nature of Claim: TP Claim No: 2295463896SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC2826B**
Make & Model: KIA CARENS, 1.7 (A) Engine No: D4FDJH553022
Reg. Date: 26/06/2018 (Man. Year: 2018) Chassis No: KNAHU815VJ7208252
Colour: Red Odometer: 46114 km
Engine Capacity: 1685 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 25/11/2020
Date Inspected: 16/12/2020 Inspected At: Jementah Motor Works (HQ)
14 Defu Lane 10, #01-406
Singapore 539195
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|----------------------------|-----------|--------------------------|-------------|-------------|
| 1 | 1 | | *REAR BUMPER | Repair | 0.00 F | *- F | |
| 2 | 1 | | *REAR BUMPER CLIPS | Necessary | 0.00 F | *- F | |
| 3 | 1 | | *REAR LH FENDER | Repair | 0.00 F | *- F | |
| 4 | 1 | | *REAR LH WHEEL RIM | Cut | 0.00 F | *- F | |
| 5 | 1 | | *REAR LH DOOR | Repair | 0.00 F | *- F | |
| 6 | 1 | | *REAR LH WHEEL HUB BEARING | Jammed | 0.00 F | *- F | |
| 7 | 1 | | *REAR LH SHOCK ABSORBER | * Check | 0.00 F | *- F | |
| | | | | | Total Parts (S\$) | 0.00 | 0.00 |

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >