

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20013011/KPS3Q2

Date: 08/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070015743

Claimant
Vehicle No : SMS5150M **Insured Vehicle No :** SLA2762Z

Date of Loss: 20/11/2020 Nature of Claim: TP Claim No: 3123620891SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS5150M		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2G73315
Reg. Date:	28/02/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU703091068
Colour:	Metallic Red	Odometer:	55367 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 7 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,918.50	4,913.25	5,005.25	50.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,840.00	1,820.00	3,020.00	62.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,758.50	6,733.25	8,025.25	54.38
+ GST 7.00/7.00% (S\$)	1,033.10	471.33	561.77	54.38
Nett Amount (S\$)	15,791.60	7,204.58	8,587.02	54.38
+ Car Rental (6.0 x S\$65.00/day) (S\$)		390.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,602.03		
Global Sum Settlement (S\$)		7,600.00		

INSPECTION

Date of Assignment: 23/11/2020

Date Inspected: 23/11/2020 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,REAR BUMPER	Bent/Cracked	485.60 FL	*485.60 FL
2	1		*ABSORBER ASSY,SHOCK,REAR LH	No such part	127.00 FL	*- FL
3	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	*332.70 FL
4	1		*GUARD,REAR BUMPER,CENTER	Cracked	374.50 FL	*374.50 FL
5	1		*REFLECTOR ASSY,REFLEX,LH	Cracked	39.00 FL	*39.00 FL
6	1		*COVER,REAR BUMPER,LOWER	Serviceable	22.00 FL	*- FL
7	1		*RETAINER,REAR BUMPER SIDE,LH	Distorted	132.60 FL	*132.60 FL
8	1		*RETAINER,REAR BUMPER SIDE,RH	Serviceable	132.60 FL	*- FL
9	1		*PANEL SUB-ASSY,BACK DOOR	Bent	1,147.80 FL	*1,147.80 FL
10	1		*HINGE ASSY,BACK DOOR,LH	Repair	61.00 FL	*- FL
11	1		*HINGE ASSY,BACK DOOR,RH	Repair	61.00 FL	*- FL
12	1		*STAY ASSY,BACK DOOR,LH	Serviceable	242.50 FL	*- FL
13	1		*STAY ASSY,BACK DOOR,RH	Serviceable	242.50 FL	*- FL
14	1		*GLASS,BACK WINDOW FIX	Shattered	761.40 FL	*761.40 FL
15	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Cracked	913.60 FL	*913.60 FL
16	1		*ORNAMENT SUB-ASSY,BACK DOOR	Necessary	47.90 FL	*47.90 FL
17	1		*PLATE,LUGGAGE COMPARTMENT DOOR NAME,NO 2	Necessary	54.60 FL	*54.60 FL
18	1		*PLATE,BACK DOOR NAME NO 1	Necessary	54.60 FL	*54.60 FL
19	1		*LENS & BODY,REAR COMBINATION LAMP,NO.2 RH	Serviceable	261.00 FL	*- FL
20	1		*LENS & BODY,REAR COMBINATION LAMP,RH	Serviceable	339.60 FL	*- FL
21	1		*LENS & BODY,REAR COMBINATION LAMP,NO.2 LH	Cracked	261.00 FL	*261.00 FL
22	1		*LENS & BODY,REAR COMBINATION LAMP,LH	Cracked	339.60 FL	*339.60 FL
23	1		*PANEL SUB-ASSY,QUARTER,LH	Repair	871.50 FL	*- FL
24	1		*PANEL SUB-ASSY,QUARTER,RH	Repair	871.50 FL	*- FL
25	1		*DUCT ASSY,QUARTER VENT,LH	Serviceable	67.00 FL	*- FL
26	1		*LINER,REAR WHEEL HOUSE,LH	Serviceable	139.80 FL	*- FL
27	1		*LINER,REAR WHEEL HOUSE,RH	Serviceable	139.80 FL	*- FL
28	1		*PANEL SUB-ASSY,BODY LOWER BACK	Bent	651.00 FL	*651.00 FL
29	1		*COVER,FLOOR UNDER NO,1 (LH)	Distorted	175.10 FL	*175.10 FL
30	1		*COVER,FLOOR UNDER NO,2 (RH)	Serviceable	241.90 FL	*- FL
31	1		*COVER,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
32	1		*PAN,REAR FLOOR	Repair	583.40 FL	*- FL
33	1		*BOX,DECK FLOOR,LH	Serviceable	313.00 FL	*- FL
34	1		*SET PARKING AID	Shorted	700.00 FS	*220.00 FS
35	1		*SET REAR BUMPER CLIP	Necessary	85.00 FS	*55.00 FS
36	1		*WHEELHOUSE LINER CLIP	Not Necessary	70.00 FS	*- FS
37	1		*BUMPER CENTRE GUARD CLIP	Not Necessary	80.00 FS	*- FS
38	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
39	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
40	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	*- FS
41	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
42	1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
43	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*80.00 FS
44	1		*WINDSCREEN MOULDING	Necessary	200.00 FS	*200.00 FS
45	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	12,598.00	6,356.00
				- List Item Discount on L Items 25.00/25.00% (S\$)	2,679.50	1,442.75
				Total Parts (S\$)	9,918.50	4,913.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	60.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	600.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	880.00
6	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	180.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			4,840.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >