

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013012/ETF3E2

Date: 15/12/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00002692000
Claimant Vehicle No :	SLQ4720Y	Insured Vehicle No :	SGK2176Y
Date of Loss:	21/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204523/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ4720Y	Engine No:	4A92CN8878
Make & Model:	MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)	Chassis No:	JMYSRCY1AGU006567
Reg. Date:	12/07/2017 (Man. Year: 2017)	Odometer:	67344 km
Colour:	White		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55Z R16	Rear Tyre Size:	205/55Z R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,739.20	2,359.60	2,379.60	50.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,320.00	490.00	27.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,549.20	3,679.60	2,869.60	43.82
Approved Total (Overridden) (\$\$)		2,950.00		
Nett Amount (\$\$)	6,549.20	2,950.00	3,599.20	54.96

INSPECTION

Date of Assignment:	25/11/2020	Car Pro Auto (HQ)
Date Inspected:	26/11/2020 Inspected At:	Blk 6 Yew Tee Industrial Estate 399-J, Woodlands Road
Estimated Period of Repair:	6.0 days	Singapore 678008

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2020)
Parts:	143	mitsubishi lancer 1.6 ex at led tail lamp (a) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ4720Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	750.00 FL	*750.00 FL
2	1		*REAR BUMPER CENTRE RETAINER	Not Necessary	160.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Broken	45.00 FL	*45.00 FL
4	1		*REAR BUMPER FASTENERS	Not Necessary	30.00 FL	*- FL
5	1		*TAILLAMP ASSY RH	Broken	485.00 FL	*404.00 FL
6	1		*TAILLAMP FASTENERS RH	Not Necessary	20.00 FL	*- FL
7	1		*TAILLAMP INNER PANEL RH	Not Necessary	58.00 FL	*- FL
8	1		*REAR RH ABSORBER	Not Necessary	395.00 FL	*- FL
9	1		*REAR RH WHEEL BEARING	Not Necessary	335.00 FL	*- FL
10	1		*REAR RH LOWER ARM	Not Necessary	360.00 FL	*- FL
11	1		*REAR RH KNUCKLE ARM	Not Necessary	410.00 FL	*- FL
12	1		*REAR WINDSCREEN MOULDING	Necessary	155.00 FL	*122.00 FL
13	1		*RH REAR FENDER	Dented	830.00 FL	*830.00 FL
14	1		*REAR FENDER INNER SHIELD RH	Torn	195.00 FL	*83.00 FL
15	1		*REAR FENDER INNER SHIELD FASTENERS RH	Torn	20.00 FL	*10.00 FL
16	1		*REAR FENDER INNER TRIM RH	Not Necessary	310.00 FL	*- FL
17	1		*REAR FENDER INNER TRIM FASTENERS RH	Not Necessary	30.00 FL	*- FL
18	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
19	1		*REAR RH RIM	Cut	300.00 FS	*300.00 FS
20	1		*REAR RH TYRE	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,198.00	2,584.00
- List Item Discount on L Items 10.00/10.00% (S\$)	458.80	224.40
Total Parts (S\$)	4,739.20	2,359.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS	New	600.00	600.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS. TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	600.00	400.00
3	TO REMOVE AND REINSTALL BOOTLID COMPONENTS	New	80.00	0.00
4	TO CHECK WIRING SYSTEM FOR PROPER FUNCTION	New	50.00	30.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	100.00	50.00
6	TO CARRY OUT ANTI RUST TREATMENT	New	100.00	30.00
7	TO REMOVE AND REINSTALL REVERSE SENSOR	New	80.00	30.00
8	TO PERFORM 4 WHEEL ALIGNMENT	New	80.00	60.00
9	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	120.00	120.00
Gross Labour Cost (S\$)			1,810.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >