

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20013015/KVF3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SHB7919Z **Insured Vehicle No :** GBE5388Z

Date of Loss: 24/11/2020 **Nature of Claim:** TP **Claim No:** CDMCG20001751

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7919Z		
Make & Model:	HYUNDAI 130, 1.6 FD (A)	Engine No:	2ZR2C51301
Reg. Date:	30/08/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU003083328
Colour:	Metallic Pearl White/Red	Odometer:	93283 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,836.67	5,479.80	6,356.87	53.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,480.00	2,110.00	58.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,426.67	6,959.80	8,466.87	54.88
+ GST 7.00/7.00% (S\$)	1,079.87	487.19	592.68	54.88
Nett Amount (S\$)	16,506.54	7,446.99	9,059.55	54.88

INSPECTION

Date of Assignment: 25/11/2020

Date Inspected: 25/11/2020 Inspected At:

Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts:	143	HYUNDAI 130 1.6 FD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB7919Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Cracked	516.00 FL	*516.00 FL
2	1		*RETAINER ,REAR BUMPER SIDE ,LH	Distorted	116.50 FL	*116.50 FL
3	1		*UNIT ,HEADLAMP ,LH	Mtg Cracked	1,781.10 FL	*1,781.10 FL
4	1		*COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1	Serviceable	960.50 FL	*- FL
5	1		*LAMP ASSY ,FOG ,LH	Serviceable	951.40 FL	*- FL
6	1		*PANEL SUB-ASSY ,FRONT DOOR ,LH	Bent	1,300.70 FL	*1,300.70 FL
7	1		*WEATHERSTRIP ,FRONT DOOR ,LH	Serviceable	231.30 FL	*- FL
8	1		*HINGE ASSY ,FRONT DOOR ,LOWER LH	Repair	110.60 FL	*- FL
9	1		*HINGE ASSY ,FRONT DOOR ,UPPER LH	Repair	97.50 FL	*- FL
10	1		*TAPE, BLACK OUT NO.1 FRT LH	Necessary	13.30 FL	*13.30 FL
11	1		*TAPE, BLACK OUT NO.2 FRT LH	Necessary	43.50 FL	*43.50 FL
12	1		*TAPE, BLACK OUT NO.3 FRT LH	Necessary	26.30 FL	*26.30 FL
13	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT LH	Serviceable	926.00 FL	*- FL
14	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,LH	Serviceable	238.30 FL	*- FL
15	1		*MOULDING ,FRONT DOOR WINDOW FRAME ,FRONT LH	Serviceable	38.60 FL	*- FL
16	1		*WEATHERSTRIP ,FROTN DOOR FIX WINDOW LH	Serviceable	76.40 FL	*- FL
17	1		*FENDER SUB-ASSY FRONT LH	Bent	977.80 FL	*977.80 FL
18	1		*EMBLEM SIDE PANEL	Necessary	54.60 FL	*54.60 FL
19	1		*LINER ,FRONT FENDER ,LH	Cracked	202.50 FL	*202.50 FL
20	1		*MIRROR ASSY -OUTER REAR VIEW ,LH	Cracked	1,339.30 FL	*1,339.30 FL
21	1		*COVER SUB-ASSY ,FRONT PILLAR UPR LH	Serviceable	100.40 FL	*- FL
22	1		*MOULDING ,WINDSHIELD ,OUTSIDE LH	Serviceable	85.50 FL	*- FL
23	1		*MOULDING ASSY ,BODY ROCKER PANEL LH	Buckled	594.80 FL	*594.80 FL
24	1		*REINFORCE SUB-ASSY ,ROCKER OUTER LH	Repair	583.40 FL	*- FL
25	1		*REINFORCEMENT SUB-ASSY ,ROCKER PANEL LH	Repair	343.40 FL	*- FL
26	1		*FENDER CLIP	Necessary	65.00 FS	*65.00 FS
27	1		*FENDER LINER CLIP	Repeated	65.00 FS	*- FS
28	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*65.00 FS
29	1		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	65.00 FS	*- FS
30	1		*FRT DOOR STICKER	Necessary	100.00 FS	*60.00 FS
31	1		*TYRE	Serviceable	350.00 FS	*- FS
32	1		*RIM	Serviceable	1,879.40 FS	*- FS
33	1		*RIM COVER	Serviceable	400.00 FS	*- FS
34	1		*SET CLIP ,ROCKER PANEL MOULDING	Necessary	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,764.10 7,221.40
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,927.43 1,741.60

Total Parts (\$\$) 11,836.67 5,479.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	500.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	900.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	60.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			3,590.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >