

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 249Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TORN	1,385.00	1,385.00
1	N/S BUMPER RETAINER	NECESSARY	87.00	87.00
1	SET REAR BUMPER CLIP	NECESSARY	40.00	40.00
	LESS 25% DISCOUNT		-	-378.00
			1,512.00	1,134.00
	<u>LABOUR</u>			
	TO DISMANTLE DAMAGED PARTS,PANEL BEAT,REPAIR.		400.00	200.00
	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA.		500.00	200.00
	ANTI RUST.	NOT NECESSARY	50.00	-
			950.00	400.00
	GRAND TOTAL		2,462.00	1,534.00

RECOMMENDED COST OF LUMP SUM REPAIRS		1,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO20013018/AUvf3q2

CHUA KANG SENG

Licensed Appraiser