

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013020/UGS3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100415128

Claimant
Vehicle No : SJQ4573D **Insured Vehicle No :** SFX1002R

Date of Loss: 25/11/2020 Nature of Claim: TP Claim No: 5727203722SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ4573D	Engine No:	G4FC9U619707
Make & Model:	HYUNDAI AVANTE, 1.6 HD (A)	Chassis No:	KMHU41BR9U756739
Reg. Date:	13/05/2009 (Man. Year: 2009)	Odometer:	180576 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,836.10	2,487.36	2,348.74	48.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,550.00	590.00	27.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,976.10	4,037.36	2,938.74	42.13
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,976.10	3,200.00	3,776.10	54.13
+ GST 7.00/7.00% (S\$)	488.33	224.00	264.33	54.13
Nett Amount (S\$)	7,464.43	3,424.00	4,040.43	54.13
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,854.00		

INSPECTION

Date of Assignment: 25/11/2020

Date Inspected: 25/11/2020 Inspected At:

Stytech Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #02-30, Kaki Bukit
Autohub
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	985.00 F	*- FL
2	1		*REAR BOOTLID EMBLEM	Necessary	35.00 F	*35.00 FL
3	1		*REAR BOOTLID AVANTE PLATE	Necessary	31.00 F	*31.00 FL
4	1		*REAR BOOTLID LOCK	Serviceable	138.50 F	*- FL
5	1		*REAR TAILLAMP RIGHT	Cracked	585.20 F	*366.00 FL
6	1		*REAR BUMPER	Deformed	486.00 F	*486.00 FL
7	1		*REAR BUMPER CHIPS	Necessary	30.00 FS	*30.00 FS
8	1		*REAR BUMPER BRACKET	Bent	79.00 F	*30.00 FL
9	1		*REAR BUMPER SPONGE	Torn	129.00 F	*129.00 FL
10	1		*REAR BUMPER LOWER LIP	Cracked	750.00 FS	*750.00 FS
11	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
12	1		*REAR PANEL	Repair	580.20 F	*- FL
13	1		*REAR PANEL GARNISH	Twisted	160.40 F	*160.40 FL
14	1		*WHETHER STRIPE	Twisted	120.80 F	*120.80 FL
15	1		*REAR BUMPER REINFORCEMENT	Cracked	270.00 F	*270.00 FL
16	2		*REAR BUMPER REINFORCEMENT BRACKETS	Bent	256.00 F	*256.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,836.10	2,864.20
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	376.84
Total Parts (\$\$)	4,836.10	2,487.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INTERIOR UPHOLSTERY	New	150.00	80.00
2	TRANSFER BOOTLID	New	150.00	0.00
3	CHECK WIRING	New	60.00	20.00
4	ANTI RUST PROOFING	New	80.00	0.00
5	PANEL BEATING	New	800.00	600.00
6	PAINT WORK	New	900.00	850.00
Gross Labour Cost (\$)			2,140.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >