

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A1620013020/4953

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

574 45739

at Workshop m/s

styler

of

Insured:

STX1002R

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

38

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

574 45739

Yr Regn:

5109

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Hyundai; Avante

c.c 1591

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

180576

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHDU41BR9U756739

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45-R17

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

25/11/20

D.O.I.

25/11/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Coe 31-3-2029 LTA #21312

30/11/20 L/S # 3200 confirmed with w.r.ston.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) ___ S + RS, ___ SI

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

SJQ4573D

Make & Model:

Hyundai Advante

Chassis No:

S/N	Parts/Labour	QTY	Condition	Price	Recommend
1	Rear Bootlid			\$ 985.00	R X
2	Rear Bootlid Emblem			\$ 35.00	Rec ✓
3	Rear Bootlid AVANTE Plate			\$ 31.00	Rec ✓
4	Rear Bootlid Lock			\$ 138.50	See X
5	Rear Taillamp Right 366.00			\$ 585.20	Cne ✓
6	Rear Bumper			\$ 486.00	De ✓
7	Rear Bumper Chips			\$ 30.00 SN	Rec ✓ s/w
8	Rear Bumper Bracket (right) 30.00			\$ 79.00	Self ✓
9	Rear Bumper Sponge			\$ 129.00	Top ✓
10	Rear Bumper Lower Lip			\$ 750.00 SN	Cne ✓ s/w
11	Reverse Sensor 1 set			\$200 SN	should ✓ s/w
12	Rear Panel			\$ 580.20	R X
13	Rear Panel Garnish			\$ 160.40	tw ✓
14	Whether Stripe			\$ 120.80	tw ✓
15	Rear bumper reinforcement			\$ 270.00	Cne ✓
16	Rear bumper reinforcement brackets	2	@ 128	\$ 256.00	Self ✓
17					
18	make cocilio				
19	not Adhorm				
20	adw				
21	1/5 \$3200				
22	4 days				
23	the 2nd After up				

Labour				
	Interior Upholstery		\$ 150.00	80
2	Transfer Bootlid		\$ 150.00	11X
3	Check Wiring		\$ 60.00	20
4	Anti Rust Proofing		\$ 80.00	11X
5	Panel Beating		\$ 800.00	600
6	Paint Work		\$ 900.00	850

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #02-03 01-03
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

Email: stytechent@singnet.com.sg

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1884.20
 202
 P-1507.36
 S/N- 980.00
 L- 1550.00
 4037.36
 202
 3229.