

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013029/ARA3Q2

Date: 05/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800035317

Claimant
Vehicle No : SMX8889U **Insured Vehicle No :** SLZ45S

Date of Loss: 23/11/2020 Nature of Claim: TP Claim No: 8146204990SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX8889U		
Make & Model:	MERCEDES-BENZ C200 AMG LINE, 2.0 (A)	Engine No:	26491530028421
Reg. Date:	15/01/2020 (Man. Year: 2018)	Chassis No:	WDD2050772R449344
Colour:	Black	Odometer:	4129 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	AGATE 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,348.20	8,222.90	10,125.30	55.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	1,930.00	3,390.00	63.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,668.20	10,152.90	13,515.30	57.10
Approved Total (Overridden) (\$\$)		8,100.00		
Nett Amount (\$\$)	23,668.20	8,100.00	15,568.20	65.78
+ Car Rental (7.0 x S\$120.00/day) (\$\$)		840.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		8,976.45		

INSPECTION

Date of Assignment: 25/11/2020

Date Inspected: 26/11/2020 Inspected At:

Ishare Auto Pte. Ltd. (HQ)
8 KAKI BUKIT AVENUE 4 #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,147.00 FL	*1,590.00 FL
2	1		*REAR BUMPER CHROME MOULDING (CENTRE)	Cut	323.00 FL	*323.00 FL
3	1		*REAR BUMPER TOWING COVER	Not Necessary	95.00 FL	*- FL
4	1		*REAR BUMPER LOWER DIFFUSER	Deformed	349.00 FL	*349.00 FL
5	2		*REAR BUMPER EXHAUST CHROME PIPE	Not Necessary	1,026.00 FL	*- FL
6	2		*REAR BUMPER EXHAUST CHROME PIPE SUPPORT BRACKET	Not Necessary	220.00 FL	*- FL
7	4		*REAR BUMPER SENSOR	Damaged (2 PCS ONLY)	880.00 FL	*440.00 FL
8	6		*REAR BUMPER SENSOR HOLDER	Not Necessary	60.00 FL	*- FL
9	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	258.00 FL	*- FL
10	2		*REAR BUMPER CENTER UPPER SIDE BRACKET	Not Necessary	90.00 FL	*- FL
11	1		*REAR BUMPER INNER LOWER CENTER FRAME	Cracked	133.00 FL	*133.00 FL
12	2		*REAR BUMPER CORNER BRACKET	Not Necessary	152.00 FL	*- FL
13	2		*REAR BUMPER SIDE RETAINER	Not Necessary	136.00 FL	*- FL
14	2		*REAR BUMPER LOWER BRACKET (CENTER)	Not Necessary	76.00 FL	*- FL
15	1		*REAR BUMPER CENTRE UPPER FRAME	Cracked	144.00 FL	*144.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Dented	817.00 FL	*684.00 FL
17	1		*TAILLAMP	N/S Cracked	1,710.00 FL	*785.00 FL
18	2		*TAILLAMP PANEL	Not Necessary	418.00 FL	*- FL
19	2		*REAR FENDER DRAIN GARNISH	Not Necessary	138.00 FL	*- FL
20	2		*REAR FENDER COWLING	Not Necessary	494.00 FL	*- FL
21	2		*REAR FENDER INNER TRIM	Not Necessary	696.00 FL	*- FL
22	1		*BOOTLID	Dented	2,660.00 FL	*2,323.00 FL
23	1		*BOOTLID CENTER CHROME MOULDING	Necessary	171.00 FL	*171.00 FL
24	1		*BOOTLID LOGO	Necessary	62.00 FL	*62.00 FL
25	1		*BOOTLID EMBLEM C200	Necessary	114.00 FL	*114.00 FL
26	4		*BOOTLID STOPPER	Not Necessary	60.00 FL	*- FL
27	2		*BOOTLID HINGE	Not Necessary	622.00 FL	*- FL
28	1		*BOOTLID INSULATOR	Not Necessary	296.00 FL	*- FL
29	1		*BOOTLID TOP LOCK	Not Necessary	380.00 FL	*- FL
30	1		*BOOTLID LOWER LOCK	Not Necessary	48.00 FL	*- FL
31	1		*BOOTLID WEATHERSTRIP	Cut	247.00 FL	*247.00 FL
32	1		*BOOTLID NUMBER PLATE LAMP GARNISH	Not Necessary	266.00 FL	*- FL
33	1		*REAR END PANEL	Dented	1,748.00 FL	*1,445.00 FL
34	1		*REAR END INNER PANEL	Repair	399.00 FL	*- FL
35	1		*REAR END PANEL INNER GARNISH	Cracked	171.00 FL	*171.00 FL
36	1		*REAR STORAGE BOX	Not Necessary	76.00 FL	*- FL
37	1		*REAR FLOOR PANEL COVER BOARD	Not Necessary	475.00 FL	*- FL
38	1		*REVERSE CAMERA	Not Necessary	741.00 FL	*- FL
39	1		*REAR NUMBER PLATE (SPECIAL TYPE)	Not Necessary	180.00 FS	*- FS
40	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
41	1		*SET REAR BUMPER BOTTOM CENTER GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
42	1		*BOOTLID SEALANT	Not Necessary	150.00 FS	*- FS
43	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
44	1		*SET BOOTLID CENTER MOULDING CLIP	Not Necessary	50.00 FS	*- FS
45	1		*SET BOOTLID NUMBER PLATE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
46	1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
47	2		*TAILLAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
48	1		*SET REAR FENDER DRAIN GARNISH CLIP	Not Necessary	80.00 FS	*- FS
49	1		*SET REAR FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
51	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
52	1		*REAR END INNER PANEL SEALANT	Not Necessary	150.00 FS	*- FS
53	1		*SET REAR END PANEL INNER GARNISH CLIP	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,238.00	9,121.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,889.80	898.10

Total Parts (S\$)	18,348.20	8,222.90
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPALCING PARTS	New	1,600.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	350.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	380.00	60.00
6	TRANSFER BOOTLID MECHANISM	New	80.00	80.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
10	REAR CHASSIS ALIGNMENT	New	250.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	620.00	0.00
Gross Labour Cost (\$)			5,320.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >