

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/FWD19008406/GGS3Q2-2

**Date:** 20/01/2021

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00001360-01

**Claimant**  
**Vehicle No :** GW4063M **Insured Vehicle No :** SLH7814M

Date of Loss: 06/05/2019 Nature of Claim: TP Claim No: 1201900012184

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GW4063M</b>	Engine No:	5L5335483
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JTFUF34YX03001227
Reg. Date:	24/06/2003 (Man. Year: 2003)	Odometer:	329273 km
Colour:	Silver		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175 R14	Rear Tyre Size:	155 R12
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,890.27	45.00	1,845.27	97.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	600.00	1,210.00	66.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>3,700.27</b>	<b>645.00</b>	<b>3,055.27</b>	<b>82.57</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>Nett Liability (S\$)</b>		<b>825.00</b>		

### INSPECTION

Date of Assignment: 16/04/2020

Date Inspected: 13/05/2019 Inspected At:

Rhino Repairs Pte Ltd (HQ)  
160 SIN MING DRIVE #03-14, SIN  
MING AUTOCITY  
Singapore 575722

Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 27 May 2020)	
<b>Parts:</b>	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GW4063M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Repair	1,218.60 FL	*- FL
2	1		*TAILGATE TOYOTA WORD STICKER	Not Necessary	100.00 FL	*- FL
3	1		*TAILGATE LOWER LATCH LEVER	Not Necessary	157.20 FL	*- FL
4	1		*TAILGATE LOWER LATCH EYE	Not Necessary	49.00 FL	*- FL
5	1		*RH TAILLAMP ASSY	Not Necessary	201.60 FL	*- FL
6	1		*RH TAILLAMP BRACKET	Not Necessary	51.60 FL	*- FL
7	1		*REAR NUMBER PLATE HOLDER	Not Necessary	157.10 FL	*- FL
8	1		*TAILGATE STOPPER	Not Necessary	38.60 FL	*- FL
9	1		*TAILGATE STOPPER BRACKET	Not Necessary	69.90 FL	*- FL
10	1		*TAILGATE DYNA STICKER	Not Necessary	78.10 FL	*- FL
11	1		*TAILGATE 13 PAX STICKER	Necessary	15.00 FS	*15.00 FS
12	1		*TAILGATE 70 KM/H STICKER	Necessary	15.00 FS	*15.00 FS
13	1		*REAR NUMBER PLATE	Scratched	45.00 FS	*15.00 FS
14	1		*SET REVERSE SENSOR BRACKET	Not Necessary	24.00 FS	*- FS
15	1		*SET REVERSE SENSOR	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,420.70</b>	<b>45.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	530.43	0.00
<b>Total Parts (\$\$)</b>	<b>1,890.27</b>	<b>45.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK AND REPAIR WIRING	New	30.00	0.00
2	TO INSTALL REVERSE SENSORS AND CHECK SENSING FUNCTION	New	60.00	0.00
3	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO VEHICLE	New	800.00	200.00
4	SPRAY PAINTING OF THE AFFECTED TAILGATE, REAR DECK PANEL	New	800.00	400.00
5	TO APPLY ANTI RUST CHEMICAL ON REPAIR AND REPLACED PANEL	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,810.00</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >