

ASS. REC. BY:

REF:

CS/AIG 20013033/Eg f3

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

1900258079

Claims No.

1993599249SG

Sum Insured:

Excess:


600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

85K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMA 97460

Yr Regn:

13/12/19

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c

1591

Colour:

ay

A/C:

Insured / Std / NI / N

Sp. Reading

7256

T/Radlo: Insured / Std / NI / N

Eng/No:

C/No:

KNAF541611E5259852

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☐ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☐ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ NII / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

195/50R15

R:

11

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

23/11/20

D.O.I.

26/11/20

Survey held at

cycle & Carriage

Des. of Damages: ☐ Frt / ☐ Rear / ☒ KOIS / ☐ NIS / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Desktop Surv - vehicle not in

~~MAX 67K~~

27/11/20@11.44am revert to AIG via Merimen.

30/11/20@9.29am Lois Chang informed C/A via Merimen.

30/11/20@10.33am Informed Kevin Leong C/A & ex:\$600 by email.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS, \$

Photos

Others

TOTAL

Pop. Form 1:

Lump Sum / L.E. / C.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
VINCENT LIM TENG KEAT	Cust No/Name LCV11684/VINCENT LIM TENG KEAT
BLK 109 JALAN BUKIT MERAH	Reg No/Reg Date SMQ9746D / 13/12/201
#04-1746	Date In/Mileage / 0
SINGAPORE 160109	Chassis No KNAF5416ML5059852
Contact No	Engine No G4FGKH738876
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV11684	CRDVCH	25/11/2020/ 09:22	QUK	282 / Kevin Leong	24790

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR ON FRT RH FENDER, FRT RH DOOR & REAR RH DOOR				200 600.00
E PNT98000 PAINT WORK ON FRT RH FENDER, FRT RH DOOR & REAR RH DOOR				1050.00
M SUNDRY PERFORM RUST PREVENTION				40 120.00
A 54900099 CHASSIS ELECTRICAL FREE TEXT				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREA				240.00
M SUNDRY SUNDRIES				20 50.00

Estimate

*Steve (CLKK) OD - NM AL
 Excess - ?
 4 days
 By Bol SM
 26/11/20, 4.00pm*

Confirm & accepted by

7% GST on	Nett 2210.00	2,210.00
		154.70
	Total Payable	2,364.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.