

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013038/EGS3Q2
Date: 27/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900106180
Claimant Vehicle No :	SLS3374J	Insured Vehicle No :	SML9079Y
Date of Loss:	12/11/2020	Nature of Claim:	TP
		Claim No:	6659697168SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS3374J		
Make & Model:	KIA CERATO, 1.6 SUNROOF (A)	Engine No:	G4FGHH678898
Reg. Date:	20/09/2017 (Man. Year: 2017)	Chassis No:	KNAFZ411MJ5740249
Colour:	Red	Odometer:	77568 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,652.00	1,197.00	1,455.00	54.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,760.00	750.00	29.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,162.00	2,957.00	2,205.00	42.72
+ GST 7.00/7.00% (S\$)	361.34	206.99	154.35	42.72

Nett Amount (S\$)	5,523.34	3,163.99	2,359.35	42.72
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,700.99		

INSPECTION

Date of Assignment: 26/11/2020

Date Inspected: 07/12/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)

209 Pandan Gardens

Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER -RR BUMPER	Repair	688.00 FS	*- FS
3	1		*COVER -RR BUMPER ,CTR	Not Necessary	315.00 FS	*- FS
4	1		*BEAM -RR BUMPER	Not Necessary	318.00 FS	*- FS
5	1		*ANTENNA ASSY -SMARTKEY	Not Necessary	69.00 FS	*- FS
6	1		*BRACKET -RR BEAM UPR MTG	Not Necessary	3.00 FS	*- FS
7	1		*BRACKET -RR BEAM UPR MTG,RH	Not Necessary	3.00 FS	*- FS
8	1		*BRACKET -RR BUMPER SIDE MTG RH	Not Necessary	29.00 FS	*- FS
9	1		*K3 BODYKIT	Broken	1,177.00 FS	*1,177.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					2,652.00	1,197.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BUMPER ,BODY KIT & AFFECTED AREA REPAIR ON REAR RH FENDER	New	160.00	400.00
2	PAINT WORK ON REAR BUMPER ,BODYKIT & REAR RH FENDER	New	1,650.00	1,050.00
3	REMOVE & INSTALL REAR PARKNG ASSIST	New	150.00	120.00
4	TO APPLY SEALANT ON AFFECTED AREA	New	50.00	0.00
5	PERFORM RUST PREVENTION	New	100.00	40.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	120.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	120.00
Gross Labour Cost (S\$)			2,510.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >