Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20013040/ATD3Q2

Date: 17/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070144544

Claimant
Vehicle No: Insured Vehicle No: GBE2962K

Date of Loss: 24/11/2020 Nature of Claim: TP Claim No: 0679216861SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMR9151P

Make & Model: VOLKSWAGEN PASSAT, 1.8 B8 TFSI AT SR Engine No: CJS132050

T7W 3G24JZ HUD (A)

Reg. Date: 15/01/2016 (Man. Year: 2015) Chassis No: WVWZZZ3CZGE117445

Reg. Date: 15/01/2016 (Man. Year: 2015) Chassis No: WVWZZZ: Colour: Odometer: 75012 km

Engine Capacity: 1798 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,006.40	4,429.39	4,577.01	50.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	560.00	1,780.00	76.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,346.40	4,989.39	6,357.01	56.03
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	11,346.40	4,000.00	7,346.40	64.75

INSPECTION

Date of Assignment: 26/11/2020

Date Inspected: 30/11/2020 Inspected At: Yi Heng Motor Workshop (HQ)

Blk 1 Kaki Bt Ave 6 #02-19

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,920.99 FL	*1,638.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	78.00 FL	*78.00 FL
3	1		*FRONT BUMPER SIDE ATTACHMENT	O/s Necessary	397.80 FL	*198.90 FL
4	1		*FRONT BUMPER INNER FRAME (RH)	Not Necessary	163.90 FL	*- FL
5	1		*FRONT BUMPER SENSOR (2 Pcs)	Damaged (1 Pc only)	487.80 FL	*243.90 FL
6	1		*FRONT BUMPER NOZZLE COVER (RH)	Not Necessary	196.90 FL	*- FL
7	1		*FRONT BUMPER NOZZLE JET (RH)	Cracked	273.75 FL	*273.75 FL
8	1		*FRONT BUMPER SPONGE	Not Necessary	288.90 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	849.90 FL	*- FL
10	1		*FRONT FENDER (RH)	Not Necessary	1,297.00 FL	*- FL
11	1		*FRONT FENDER INNER SHIELD (RH)	Not Necessary	198.60 FL	*- FL
12	10		*FRONT FENDER INNER SHIELD CLIPS (RH)	Not Necessary	78.00 FL	*-FL
13	1		*HEADLAMP (RH)	Cracked	2,996.40 FL	*2,489.00 FL
14	2		*HEADLAMP CLIPS	Not Necessary	39.92 FL	*- FL
15	1		*HEADLAMP TOP PANEL (RH)	Not Necessary	214.90 FL	*- FL
16	1		*FOGLAMP (RH)	Not Necessary	290.60 FL	*-FL
17	1		*FOGLAMP COVER (RH)	Not Necessary	233.75 FL	*- FL
F=Fra	anchise	part. L=List	ItemDisc.			
				Sub Total (S\$)	•	4,921.55
	- List Item Discount on L Items 10.00/10.00% (S\$)					492.16
				Total Parts (S\$)	9,006.40	4,429.39

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING SYSTEM	New	80.00	30.00
2	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	120.00	0.00
3	TO REMOVE/REFIX HEADLAMP ASSY,REALIGNMENT AND RESET LIGHTING SYSTEM	New	340.00	30.00
4	TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC	New	660.00	250.00
5	TO RESPRAY ON AFFECTED AREAS	New	660.00	250.00
6	TO REMOVE/REFIX FRONT BUMPER SENSOR & REPROGRAMME	New	480.00	0.00
	Gross Labo	2,340.00	560.00	
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >