

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20013041/KQF3E2
Date: 15/01/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD Policy No: 0999993880
Date of Loss: 16/11/2020 Nature of Claim: OD Claim No: 3753506952SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH7542R**
Make & Model: MERCEDES-BENZ VITO 109, 1.6 CDI LONG (M) Engine No: R9MA503C052160
Reg. Date: 14/09/2018 (Man. Year: 2018) Chassis No: WDF44760323474388
Colour: Red Odometer: 60493 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$62,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Michelin 6 mm Rear Left Side: Achilles 7 mm
Front Right Side: Michelin 6 mm Rear Right Side: Achilles 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,864.85	4,500.60	364.25	7.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,300.00	1,180.00	47.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,344.85	5,800.60	1,544.25	21.02
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	5,944.85	4,400.60	1,544.25	25.98
+ GST 7.00/7.00% (S\$)	416.14	308.04	108.10	25.98
Nett Amount (S\$)	6,360.99	4,708.64	1,652.35	25.98

INSPECTION

Date of Assignment: 26/11/2020
Date Inspected: 26/11/2020 Inspected At: Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Bent	950.00 F	*950.00 F
2	1		*BONNET HOOK (WCP)	Distorted	98.00 F	*98.00 F
3	2		*BONNET HINGES - LH/RH (WCP)	Bent / Distorted	136.00 F	*136.00 F
4	1		*BONNET SPRING - LH (WCP)	Missing	28.00 F	*28.00 F
5	1		*SUPPORT PANEL (WCP)	Cracked	350.00 F	*350.00 F
6	1		*SUPPORT PANEL TOP BRACKET - LH (WCP)	Cracked	58.00 F	*58.00 F
7	1		*HEADLAMP - LH (WCP)	Cracked	520.00 F	*520.00 F
8	1		*HEADLAMP BRACKET - LH (WCP)	Cracked	58.00 F	*58.00 F
9	1		*FRONT BUMPER (WCP)	Bent	590.00 F	*590.00 F
10	1		*FRONT BUMPER SIDE RETAINER - LH (WCP)	Distorted	58.00 F	*58.00 F
11	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	420.00 F	*420.00 F
12	1		*FRONT BUMPER INSIDE PARTS - LH (WCP)	Cracked	80.00 F	*80.00 F
13	1		*FRONT BUMPER CLIPS (WCP) (15PCS)	Necessary	90.75 FS	*50.00 FS
14	1		*FRONT FENDER - LH (WCP)	Buckled	485.00 F	*485.00 F
15	1		*FRONT FENDER INNER SHIELD - LH (WCP)	Serviceable	125.00 F	*- F
16	20		*FRONT FENDER INNER SHIELD CLIPS - LH (WCP)	Not Necessary	110.00 F	*- F
17	1		*FRONT DOOR COMPANY STICKER - LH	Not Necessary	25.00 FS	*- FS
18	1		*FRONT NUMBER PLATE (Dented)	Not Consistent With The Impact	40.00 FS	*- FS
19	1		*AIR-CLEANER ASSY (WCP)	Cracked	215.00 F	*215.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,436.75	4,096.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	428.10	404.60
Total Parts (\$\$)	4,864.85	4,500.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT AIR-CON CONDENSER, RADIATOR ASSY TO FACILITATES THE REPAIRS.	New	120.00	100.00
2	TO CHECK AND RECTIFY WIRING SYSTEM.	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN LH FRONT FENDER INNER PANEL, LH FRONT CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME.	New	1,000.00	500.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.	New	1,000.00	500.00
5	TO SUPPLY AND PASTE LETTERING ON BONNET	New	220.00	150.00
6	TO REMOVE AND REFIT AIR-CLEANER ASSY.	New	60.00	30.00
Gross Labour Cost (\$\$)			2,480.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >