Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013042/KVF3Q2

Date: 27/01/2021

Engine No:

**REFERENCE** 

China Taiping Insurance Policy No: Handling Insurer:

(Singapore) Pte. Ltd.

DMCVSNW00091022000

Claimant Vehicle No:

Reg. Date:

Colour:

**GBF9958Y** 

Vehicle No:

Insured GBK5795A

Date of Loss: 19/11/2020 Nature of TP Claim:

Claim SNM20D204485/C02/LEWLC

YD25412959A

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**GBF9958Y** Reg No:

Make & Model: NISSAN NV350, 2.5 5AT 5DR EURO V (A)

16/05/2017 (Man. Year: 2016)

Chassis No: JN1MC2E26Z0007750

Odometer: Silver 110275 km

**Engine Capacity:** 2488 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

**CONDITION OF TYRES** 

Front Tyre Size: 195R15X8 Rear Tyre Size: 195R15X8 Front Left Side: Windforce 8 mm Rear Left Side: Windforce 8 mm Front Right Side: Windforce 8 mm Rear Right Side: Windforce 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,280.00	1,000.00	280.00	21.88
Miscellaneous Items	40.00	40.00	0.00	0.00
Labour	1,530.00	1,440.00	90.00	5.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,850.00	2,480.00	370.00	12.98
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	2,850.00	1,950.00	900.00	31.58
+ GST 7.00/7.00% (S\$)	199.50	136.50	63.00	31.58
Nett Amount (S\$)	3.049.50	2.086.50	963.00	31.58

**INSPECTION** 

Date of Assignment: 26/11/2020 Present Location: Cheng Hoe Motor Pte Ltd (Yishun) Date Inspected: 04/01/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A Singapore 768761

Estimated Period of Repair: 5.0 days

Manager: VERON CHEN Adjuster: KENNETH KONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference			
Part Source:	:	(Last Synchronised: 26 Jan 2021)	
Parts:	N/A	NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	rint Code: (Unsubmitted, no print-code for GBF9958Y)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER	Serviceable	280.00 F	*- FS
2	1		*1 PC FRT RH HEADLAMP	Cracked	210.00 F	*210.00 FS
3	1		*1 PC FRT PANEL	Bent	480.00 F	*480.00 FS
4	1		*1 PC FRT GRILLE	Dented	310.00 F	*310.00 FS
F=Fra	anchise	part. S=SpcNe	ett.	_		
				Total Parts (S\$)	1,280.00	1,000.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellan	eous Items			
1	1	1 PC FRT WINDSCREEN SEALANT		40.00	40.00
		(Necessary)			
			Sub Total (S\$)	40.00	40.00

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	1) TO REMVOVE AND REFIX FRT WINDSCREEN GLASS	New	100.00	100.00
2	2) TO REMOVE AND REFIX DASH BOARD, METER ASSY TO FACILITATE ON REPAIRS	New	230.00	220.00
3	3) TO REMOVE AND REFIX AIRCON, CHECK AND VACUUM GAS	New	100.00	100.00
4	4) TO PANEL BEATING	New	550.00	520.00
5	5) TO PUTTY AND RESPRAY ON FRT PANEL, FRT RH FENDER, FRT BUMPER	Repair 	550.00	500.00
	Gross Labou	ır Cost (S\$)	1,530.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >