

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 6596J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BENT	1,812.00	1,480.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	80.00	80.00
1	REAR BUMPER SIDE RETAINER -RH (CONSISTENT)	SERVICEABLE	98.50	-
1	REAR BUMPER SIDE RETAINER -LH (CONSISTENT)	SERVICEABLE	98.50	-
1	REAR TAILLAMP -RH (CONSISTENT)	MTG CRACKED	725.00	635.10
1	TOWING COVER (CONSISTENT)	SERVICEABLE	85.00	-
1	REAR BUMPER CHROME MOULDING -LH (CONSISTENT)	NOT NECESSARY	110.00	-
1	REAR BUMPER CHROME MOULDING -RH (CONSISTENT)	NOT NECESSARY	110.00	-
1	REAR BUMPER CENTRE CHROME MOULDING (CONSISTENT)	NECESSARY	280.00	280.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	580.00	-
1	REAR BUMPER CENTRE BRACKET -LH (CONSISTENT)	SERVICEABLE	80.00	-
1	REAR BUMPER CENTRE BRACKET -RH (CONSISTENT)	SERVICEABLE	80.00	-
1	REAR BUMPER INNER GARNISH (CONSISTENT)	SERVICEABLE	255.10	-
	LESS 10% DISCOUNT		-	-247.51
			4,394.10	2,227.59
	SPECIAL NETT ITEMS			
1	REVERSE SENSORS (SN) (CONSISTENT)	SCRATCHED	400.00	250.00
			400.00	250.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		1,000.00	200.00
	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION .		1,200.00	250.00
	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL.	NOT NECESSARY	150.00	-
	TO CHECK DIAGNOSTICS.	NOT NECESSARY	250.00	-
	TO CHECK WIRING FUNCTIONS.		120.00	15.00
			2,720.00	465.00
	GRAND TOTAL		7,514.10	2,942.59

Report Ref No. CC4/ASM20013043/Kps3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,350.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20013043/Kps3q2

KONG SENG CHEONG

Licensed Appraiser