

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 2743P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CRUMPLED	1,077.10	850.00
2	FRONT BUMPER SIDE RETAINER	BROKEN	93.40	93.40
10	FRONT BUMPER CLIPS	NECESSARY	55.00	55.00
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	254.10	-
1	FRONT BUMPER INNER FOAM ABSORBER	SERVICEABLE	108.10	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	86.40	-
1	WIPER WASHER TANK	SERVICEABLE	210.60	-
2	HEADLAMP ASSY	CRUMPLED	1,650.80	1,582.00
1	FRONT BONNET	DENTED	916.20	916.20
1	FRONT BONNET LOCK ASSY	JAMMED	81.20	81.20
1	FRONT SUPPORT PANEL ASSY	BENT	919.00	744.00
2	FRONT FENDER	CRUMPLED	1,350.00	1,100.00
2	FRONT FENDER SPLASH SHIELD	N/S CRUMPLED	280.50	140.00
16	FRONT FENDER SPLASH SHIELD CLIPS	NECESSARY	90.00	20.00
2	FRONT FENDER 1/4 GARNISH	SERVICEABLE	80.00	-
2	FRONT FENDER VERTICAL SEAL	SERVICEABLE	70.00	-
2	FRONT SHOCK ABSORBER	N/S BENT	820.80	368.00
2	FRONT SUSPENSION LOWER ARM	N/S BENT	750.00	316.00
2	FRONT KNUCKLE ARM	N/S BENT	870.00	435.00
2	FRONT KNUCKLE ARM BEARING	N/S JAMMED	450.00	132.40
2	FRONT SHOCK ABSORBER LINK	SERVICEABLE	260.00	-
2	FRONT DRIVE SHAFT	N/S BENT	2,750.00	1,375.00
1	FRONT SUSPENSION CROSS MEMBER	TO REPAIR SEE LABOUR	2,081.00	-
1	STEERING RACK & PINION ASSY	SERVICEABLE	1,471.50	-
2	STEERING TIE ROD LH	BENT	180.00	180.00
2	STEERING TIE ROD END	SERVICEABLE	320.00	-
1	LH FRONT DOOR	TO REPAIR SEE LABOUR	1,224.30	-
1	LH FRONT DOOR WEATHERSTRIP	SERVICEABLE	186.00	-
2	BRAKE PIPE	SERVICEABLE	240.00	-

Report Ref No. CS3/CTI20002103/Qsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	ABS SENSOR W/WIRE	SERVICEABLE	220.00	-
1	RADIATOR OVERFLOW TANK	SERVICEABLE	131.70	-
2	FOG LAMP COVER	SERVICEABLE	324.50	-
1	ENGINE MOUNTING - LH	SERVICEABLE	350.00	-
1	ENGINE MOUNTING - REAR	SERVICEABLE	236.00	-
1	GEARBOX MOUNTING	CRUMPLED	265.00	246.00
	LESS 25% DISCOUNT		-5,113.30	-2,158.55
			15,339.90	6,475.65
	SPECIAL NETT ITEMS			
1	FRONT RIM LH (SN)	CUT	580.00	450.00
1	FRONT TYRE LH (SN) (\$200.00) (70%)	BROKEN	255.00	140.00
1	FRONT GRILLE (SN)	MISSING	628.50	349.00
			1,463.50	939.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		180.00	30.00
	TO ALIGN HEADLAMPS & REFOCUS HEADLAMP BEAMS.	NOT NECESSARY	180.00	-
	TO APPLY ANTI RUST UNDERCOAT.		180.00	50.00
	TO REMOVE & REFIT RADIATOR TO FACILITATE REPAIRS.		180.00	50.00
	TO REMOVE & REFIT AIRCON CONDENSER TO FACILITIES REPAIRS.		180.00	50.00
	LABOUR CHARGES TO REMOVE & REPLACE AND PANEL BEAT. INCLUSIVE OF THE REPAIR OF FRONT SUSPENSION CROSS MEMBER AND LH FRONT DOOR.		2,000.00	1,300.00
	SPRAY PAINTING TO AFFECTED PARTS.		2,000.00	1,200.00
	TO CONDUCT 4 WHEEL ALIGNMENT.		200.00	60.00
	TO REMOVE & REPLACE FRONT UNDERCARRIAGE PARTS.		180.00	200.00
	TO REMOVE & REPLACE POWER STEERING RACK AND CENTRALISE WHEEL.		280.00	100.00
	TO REMOVE AND TRANSFER FRONT DOOR GLASS AND SERVICEABLE PARTS.	NOT NECESSARY	180.00	-
	TOWING & RECOVERY SERVICE FEES.		150.00	50.00
			5,890.00	3,090.00
	GRAND TOTAL		22,693.40	10,504.65

Report Ref No. CS3/CTI20002103/Qsd3e2-1



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS	8,400.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/CTI20002103/Qsd3e2-1

Ja

OI SUN PIN

Asst. Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser