

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP20020004

Date: 20 FEB 2020

*Stars Rental & leasing
c/o D's Graffiti Concepts Pte Ltd
10 ang mo kio ind park 2A
Amk autopoint #03-13
Singapore 568047*

THIRD PARTY SURVEY ACCIDENT OCCURED ON 27 JAN 2020

Workshop Name and Address

D's Graffiti Concepts Pte Ltd
10 ang mo kio ind park 2A
Amk autopoint #03-13
Singapore 568047

As per your instruction dated 05 FEB 2020
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
SMK2743P

1. VEHICLE PARTICULARS

Registration No : SMK2743P
Model : TOYOTA ALLION A15 A
Year / Capacity : Apr 2009 / 1598 cc
Chassis No : NZT2603042958

Engine No : 1NZD379255
Mileage : N.a km
Colour : Metallic Black

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	185/65R15	Falken	9.00 mm	Normal
REAR O/S :	185/65R15	Falken	9.00 mm	Normal
FRONT N/S :	185/65R15	Falken	9.00 mm	Normal
REAR N/S :	185/65R15	Falken	9.00 mm	Normal

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 14 working days to complete
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SMK2743P

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	TP Survey Revised (S\$)	Our Revised Survey (S\$)
<u>List Items</u>				
1 pc	Front bumper	Broken	\$ 1,077.10	\$ 1,077.10
2 pcs	Front bumper side retainer	necessary	\$ 93.40	\$ 93.40
10 pcs	Front bumper clips	necessary	\$ 55.00	\$ 55.00
1 pc	Front bumper reinforcement	bent	\$ 254.10	\$ 254.10
1 pc	Front bumper inner foam absorber	distorted	\$ 108.10	\$ 108.10
1 pc	Front bumper lower grille	bent	\$ 85.40	\$ 85.40
1 pc	Wiper washer tank	crushed	\$ 210.60	\$ 210.60
2 pcs	headlamp assy	broken	\$ 1,650.80	\$ 1,650.80
1 pc	Front bonnet	damaged	\$ 915.20	\$ 915.20
1 pc	Front bonnet lock assy	damaged	\$ 81.20	\$ 81.20
1 pc	Front support panel assy	distorted	\$ 919.00	\$ 919.00
2 pcs	front fender	grazed/deformed	\$ 1,350.00	\$ 1,350.00
2 pcs	front fendr splash shield	distorted	\$ 260.50	\$ 260.50
*6 pcs	front fendr splash shield clips	necessary	\$ 90.00	\$ 90.00
2 pcs	front fender 1/4 garnish	dislodge	\$ 80.00	\$ 80.00
2 pcs	front fender vertical seal	squashed	\$ 70.00	\$ 70.00
2 pcs	Front shock absorber	distorted	\$ 820.80	\$ 820.80
2 pcs	Front suspension lower arm	distorted	\$ 750.00	\$ 750.00
2 pcs	Front knuckle arm	distorted	\$ 870.00	\$ 870.00
2 pcs	Front knuckle arm bearing	damaged	\$ 450.00	\$ 450.00
2 pcs	Front shock absorber link	damaged	\$ 260.00	\$ 260.00
2 pcs	Front drive shaft	damaged	\$ 2,750.00	\$ 2,750.00
1 pc	Front suspension cross member	damaged	\$ 2,081.00	\$ 2,081.00
1 pc	Steering rack & pinion assy	damaged	\$ 1,471.50	\$ 1,471.50
2 pcs	Steering tie rod	damaged	\$ 180.00	\$ 180.00
2 pcs	Steering tie rod end	damaged	\$ 320.00	\$ 320.00
1 pc	LH front door	dentec	\$ 1,224.30	\$ 1,224.30
1 pc	LH front door weatherstrip	deformed	\$ 186.00	\$ 186.00
2 pcs	Brake pipe	dentec	\$ 240.00	\$ 240.00
2 pcs	ABS sensor b/w re	shorted	\$ 220.00	\$ 220.00
1 pc	Radiator overflow tank	bent	\$ 131.70	\$ 131.70

Vehicle Number : SMK2743P

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	TP Survey Revised (S\$)	Our Revised Survey (S\$)
<u>List Items</u>				
2 pcs	Fog lamp cover	damaged	\$ 324.50	\$ 324.50
1 pc	Engine mounting - LH	damaged	\$ 350.00	\$ 350.00
1 pc	Engine mounting - rear	damaged	\$ 235.00	\$ 235.00
1 pc	Gear box mounting	damaged	\$ 265.00	\$ 265.00
Parts Sub-Total			\$ 20,453.20	\$ 20,453.20
Discount: 25.00%			\$ 294.38	\$ 294.38
			\$ 20,158.83	\$ 20,158.83

Vehicle Number : SMK2743P

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Net Items</u>				
1 pc	Front rim LH	dented	\$ 580.00	\$ 580.00
1 pc	Front tyre LH	scuffed	\$ 255.00	\$ 200.00
1 pc	Front gate	damaged	\$ 628.50	\$ 628.50
Special Net Sub-Total:			\$ 1,463.50	\$ 1,408.50
Spare Parts Total:			\$ 21,622.33	\$ 21,567.33

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (\$)	Our Revised Estimation (\$)
------	------------------	--------------------------	-----------------------------


Spare PartsTotal c/f \$ 21,622.33 \$ 21,567.33

1	To check wiring	\$ 180.00	\$ 150.00
2	To align headlamps & refocus headlamp beams	\$ 180.00	\$ 150.00
3	To apply anti rust undrcoat	\$ 180.00	\$ 150.00
4	To remove & refir radiator to faciliate repairs	\$ 180.00	\$ 150.00
5	To remove & refir aircon condenser to faciites repairs	\$ 180.00	\$ 150.00
6	Labour charges to remove & replace and panel beat	\$ 2,000.00	\$ 1,800.00
7	Spray painiting to affected parts	\$ 2,000.00	\$ 1,800.00
8	To conduct 4 wheel alignment	\$ 200.00	\$ 180.00
9	To remove & replace front undercarriage parts.	\$ 180.00	\$ 450.00
10	To remove & replace power steering rack and centralise wheel	\$ 280.00	\$ 250.00
11	To remove and transfer front door glass and serviceable parts	\$ 180.00	\$ 150.00
12	Towing & recovery service fees	\$ 150.00	\$ 150.00

Total \$ 27,512.33 \$ 27,097.33

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 21,700.00


Fong Kok Heng
Qualified Appraiser







UTOMAX
SERV




UTOMAX
SERV



UTOMAX
SERV









OMAX SU



AUTO SURVEY

OMAX SU



VEY

TOMAX SU



AUTO SURVEY

TOMAX SU



AUTO RVEY





OMAX S



AUTOMOTIVE
DRIVE

