

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20013051/R1BS3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SKE7907G	Insured Vehicle No :	GBJ9210A
Date of Loss:	24/11/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002522

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE7907G		
Make & Model:	HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)	Engine No:	L15A71002855
Reg. Date:	02/04/2012 (Man. Year: 2008)	Chassis No:	JHMG88509S202335
Colour:	Blue	Odometer:	186175 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,971.28	4,695.60	1,275.68	21.36
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,760.00	2,530.00	230.00	8.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,742.28	7,236.60	1,505.68	17.22
Approved Total (Overridden) (\$\$)		5,750.00		
(\$\$)	8,742.28	5,750.00	2,992.28	34.23
+ GST 7.00/7.00% (\$\$)	611.96	402.50	209.46	34.23
Nett Amount (\$\$)	9,354.24	6,152.50	3,201.74	34.23
+ Medical Costs (\$\$)		32.10		
+ Car Rental (13.0 x S\$120.00/day + 7.00% GST) (\$\$)		1,669.20		
+ Doc/Search Fee (\$\$)		7.49		
+ Other Costs (\$\$)		85.60		
Nett Liability (\$\$)		7,946.89		
Global Sum Settlement (\$\$)		7,770.00		

INSPECTION

Date of Assignment: 26/11/2020 Present Location:

Date Inspected:	26/11/2020 Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) 15 FAN YONG ROAD Repairer: Mova Automotive Pte Ltd (Bukit Merah)
Estimated Period of Repair:	11.0 days	

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2021)
Parts:	144	HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE7907G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	950.60 FL	*950.60 FL
2	1		*TAILGATE GLASS	Broken	630.50 FL	*630.50 FL
3	1		*TAILGATE GLASS MOULDING	Necessary	68.00 FL	*68.00 FL
4	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
5	1		*TAILGATE GARNISH	Serviceable	130.60 FL	*- FL
6	1		*TAILGATE LOGO	Necessary	24.80 FL	*24.80 FL
7	1		*TAILGATE EMBLEM - JAZZ	Necessary	28.60 FL	*28.60 FL
8	1		*TAILGATE WIPER ARM	Scratched	43.70 FL	*43.70 FL
9	1		*TAILGATE WIPER ARM COVER	Cracked	13.60 FL	*13.60 FL
10	1		*TAILGATE WIPER MOTOR	Serviceable	332.40 FL	*- FL
11	1		*TAILGATE LOCK	Jammed	211.90 FL	*211.90 FL
12	1		*TAILGATE WEATHERSTRIP	Necessary	92.30 FL	*92.30 FL
13	1		*TAILGATE INNER TRIM	Serviceable	255.40 FL	*- FL
14	1		*TAILGATE PULL POCKET	Serviceable	24.60 FL	*- FL
15	1		*TAILGATE LOCK STRICKER	Serviceable	41.90 FL	*- FL
16	2		*TAILGATE ASSY RH & LH	Cracked	516.80 FL	*516.80 FL
17	1		*TAILLAMP PANEL LH	Serviceable	156.90 FL	*- FL
18	2		*TAILLAMP CLIPS	Necessary	11.00 FL	*11.00 FL
19	1		*TAILLAMP LOWER BRACKET LH	Serviceable	58.40 FL	*- FL
20	1		*REAR FENDER LH	Buckled	714.20 FL	*714.20 FL
21	2		*REAR FENDER INNER TRIM RH & LH	Deformed	524.40 FL	*524.40 FL
22	1		*REAR END PANEL	Bent	364.50 FL	*364.50 FL
23	1		*REAR END PANEL INNER TRIM	Deformed	70.80 FL	*70.80 FL
24	1		*SPARE WHEEL PANEL (REPAIR) (NPA)	Repair	-	*- FL
25	1		*SPARE TYRE BOARD	Deformed	207.10 FL	*207.10 FL
26	1		*REAR TOW COVER	Serviceable	21.80 FL	*- FL
27	1		*REAR BUMPER	Deformed	894.80 FL	*894.80 FL
28	1		*REAR BUMPER LOWER GARNISH	Deformed	103.40 FL	*103.40 FL
29	1		*REAR BUMPER RETAINER LH	Necessary	18.50 FL	*18.50 FL
30	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
31	1		*REVERSE SENSOR (SET)	Not Working	200.00 FS	*200.00 FS
32	1		*REAR QUARTER GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
33	1		*REAR VIEW CAMERA	Serviceable	350.00 FS	*- FS
34	1		*REAR FENDER COWLING LH	Serviceable	85.10 FL	*- FL
35	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
36	1		*REAR CHASSIS MEMBER LH	Repair	-	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,296.60	5,799.50
- List Item Discount on L Items 20.00/20.00% (\$)	1,325.32	1,103.90
Total Parts (\$)	5,971.28	4,695.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD REAR FENDER LH, REAR END PANEL. KNOCK AND STRAIGHTEN REAR BODY MEMBER, SPARE WHEEL PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	1,200.00	1,000.00
2	SPRAY PAINT TAILGATE, REAR FENDER LH, TAILLAMP PANELS, REAR END PANEL, SPARE WHEEL PANEL, REAR BUMPER, REAR BODY MEMBER	New	1,000.00	900.00
3	REMOVE & REINSTALL TAILGATE GLASS AND CHECK WATER LEAKAGE	New	120.00	100.00
4	REMOVE & REFIT TAILGATE INNER TRIM, MECHANISM AND CHECK LOCKING SYSTEM	New	60.00	40.00
5	REMOVE & REFIT PETROL TANK, PIPE, HOSE	New	80.00	60.00
6	REMOVE & REINSTALL REVERSE SENSOR AND CHECK FUNCTION	New	50.00	40.00
7	REMOVE & REFIT REAR SEAT ASSY, UPHOLSTERY, INNER TRIM, COVERING	New	150.00	80.00
8	RUST PROOF AFFECTED AREA	New	100.00	60.00
9	TO CHECK CHASSIS ALIGNMENT ON LASER LOCK MECHAIN	New	-	250.00
Gross Labour Cost (\$\$)			2,760.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >