


TP INSURER: India International Assurance Pte Ltd (HQ)

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	24/11/2020
Vehicle Reg. No.:	SKE7907G	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ONG CHEE BING (WANG ZHIMIN)		
Make/Model:	HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)	Vehicle Reg. Date:	02/04/2012
Vehicle Colour:	BLUE		
Engine No:	L15A71002855	Chassis No:	JHMGE88509S202335
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS	Amount
Parts	5,971.28
Miscellaneous Items	11.00
Labour	2,760.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	8,742.28
+ GST 7.00% (\$\$)	611.96
Nett Amount (\$\$)	9,354.24

This claim is handled by: BILLY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Nov 2020)

Parts: 144 HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKE7907G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalog are not prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE <i>buc</i> ✓	20.00	0.00	*950.60 FL
2	1		*TAILGATE GLASS <i>buc</i> ✓	20.00	0.00	*630.50 FL
3	1		*TAILGATE GLASS MOULDING <i>neu</i> ✓	20.00	0.00	*68.00 FL
4	1		*TAILGATE GLASS SEALANT <i>neu</i> ✓	0	0.00	*40.00 FS
5	1		*TAILGATE GARNISH ?	20.00	0.00	*130.60 FL
6	1		*TAILGATE LOGO <i>neu</i> ✓	20.00	0.00	*24.80 FL
7	1		*TAILGATE EMBLEM - JAZZ <i>neu</i> ✓	20.00	0.00	*28.60 FL
8	1		*TAILGATE WIPER ARM <i>SCA</i> ✓	20.00	0.00	*43.70 FL
9	1		*TAILGATE WIPER ARM COVER <i>CA</i> ✓	20.00	0.00	*13.60 FL
10	1		*TAILGATE WIPER MOTOR ?	20.00	0.00	*332.40 FL
11	1		*TAILGATE LOCK <i>neu</i> ✓	20.00	0.00	*211.90 FL
12	1		*TAILGATE WEATHERSTRIP <i>neu</i> ✓	20.00	0.00	*92.30 FL
13	1		*TAILGATE INNER TRIM ?	20.00	0.00	*255.40 FL
14	1		*TAILGATE PULL POCKET ?	20.00	0.00	*24.60 FL
15	1		*TAILGATE LOCK STRICKER X	20.00	0.00	*41.90 FL
16	2		*TAILGATE ASSY RH & LH <i>PHOTO/LH - RUCS. CA</i> ✓	20.00	0.00	*516.80 FL
17	1		*TAILLAMP PANEL LH ?	20.00	0.00	*156.90 FL
18	2		*TAILLAMP CLIPS <i>neu</i> ✓	20.00	0.00	*11.00 FL
19	1		*TAILLAMP LOWER BRACKET LH ?	20.00	0.00	*58.40 FL
20	1		*REAR FENDER LH <i>buc</i> ✓	20.00	0.00	*714.20 FL
21	2		*REAR FENDER INNER TRIM RH & LH ?	20.00	0.00	*524.40 FL
22	1		*REAR END PANEL <i>buc</i> ✓ <i>photo</i>	20.00	0.00	*364.50 FL
23	1		*REAR END PANEL INNER TRIM ?	20.00	0.00	*70.80 FL
24	1		*SPARE WHEEL PANEL (REPAIR) R	20.00	0.00	-
25	1		*SPARE TYRE BOARD ?	20.00	0.00	*207.10 FL
26	1		*REAR TOW COVER X	20.00	0.00	*21.80 FL
27	1		*REAR BUMPER <i>de</i> ✓	20.00	0.00	*894.80 FL
28	1		*REAR BUMPER LOWER GARNISH <i>de</i> ✓	20.00	0.00	*103.40 FL
29	1		*REAR BUMPER RETAINER LH <i>neu</i> ✓	20.00	0.00	*18.50 FL
30	10		*REAR BUMPER CLIPS <i>neu</i> ✓	20.00	0.00	*30.00 FL
31	1		*REVERSE SENSOR (SET) <i>neu</i> ✓	0	0.00	*200.00 FS
32	1		*REAR QUARTER GLASS SEALANT <i>neu</i> ✓	0	0.00	*40.00 FS
33	1		*REAR VIEW CAMERA X	0	0.00	*350.00 FS
34	1		*REAR FENDER COWLING LH ?	20.00	0.00	*85.10 FL
35	1		*REAR NUMBER PLATE X	0	0.00	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 7,296.60

- List Item Discount on L Items (\$\$) 1,325.32

Total Parts (\$\$) 5,971.28

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

Amount

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$) 11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO CUT/WELD REAR FENDER LH, REAR END PANEL. KNOCK AND STRAIGHTEN REAR BODY MEMBER, SPARE WHEEL PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	1000	1,200.00
2	SPRAY PAINT TAILGATE, REAR FENDER LH, TAILLAMP PANELS, REAR END PANEL, SPARE WHEEL PANEL, REAR BUMPER, REAR BODY MEMBER	New	200	1,000.00
3	REMOVE & REINSTALL TAILGATE GLASS AND CHECK WATER LEAKAGE	New		120.00
4	REMOVE & REFIT TAILGATE INNER TRIM, MECHANISM AND CHECK LOCKING SYSTEM	New		60.00
5	REMOVE & REFIT PETROL TANK, PIPE, HOSE	New		80.00
6	REMOVE & REINSTALL REVERSE SENSOR AND CHECK FUNCTION	New		50.00
7	REMOVE & REFIT REAR SEAT ASSY, UPHOLSTERY, INNER TRIM, COVERING	New		150.00
8	RUST PROOF AFFECTED AREA	New		100.00

Gross Labour Cost (\$\$) 2,760.00

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair

Hp 90010068

11 days

4/5

26/11/2020 @ 1425

Resurvey after repair