

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI20013058/AVF3Q2**Date:** 28/01/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant**Vehicle No :** SJP3410C**Insured Vehicle No :** XE4164Z

Date of Loss: 23/11/2020

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJP3410C**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ3238266

Reg. Date: 20/03/2009 (Man. Year: 2009)

Chassis No: JTDER12W903002878

Colour: Grey

Odometer: 197478 km

Engine Capacity: 1794 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,588.17	794.25	793.92	49.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	480.00	420.00	46.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,488.17	1,274.25	1,213.92	48.79
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	2,488.17	1,000.00	1,488.17	59.81
+ GST 7.00/7.00% (S\$)	174.17	70.00	104.17	59.81
Nett Amount (S\$)	2,662.34	1,070.00	1,592.34	59.81

INSPECTION

Date of Assignment: 26/11/2020

Date Inspected: 02/12/2020 Inspected At:

Ryder Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2, #02-19 AutoHub

@ Kaki Bukit

Singapore 417921

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2021)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP3410C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	887.10 FL	*545.00 FL	
2	1		*REAR BUMPER O/S RETAINER	Necessary	113.10 FL	*65.00 FL	
3	1		*REAR O/S TAIL-LAMP	Cut	690.70 FL	*409.00 FL	
4	10		*REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS	
5	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	280.00 FS	*- FS	
					Sub Total (S\$)	2,010.90	1,049.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	422.73	254.75
					Total Parts (S\$)	1,588.17	794.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE REAR DAMAGE PARTS	New	400.00	200.00
2	TO SPRAY PAINTING	New	400.00	200.00
3	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	50.00	50.00
4	TO CHECK WIRING	New	50.00	30.00
			Gross Labour Cost (\$\$)	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >