

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20013061/GQF3E2

**Date:** 04/12/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800024980
<b>Claimant Vehicle No :</b> SLM5022T	<b>Insured Vehicle No :</b>	SLW7762A
Date of Loss: 25/11/2020	Nature of Claim: TP	Claim No: 8335547782SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM5022T		
Make & Model:	MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)	Engine No:	4A92CP0899
Reg. Date:	31/03/2017 (Man. Year: 2017)	Chassis No:	JMYSRCY1AGU006635
Colour:	Silver	Odometer:	59919 km
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	26/11/2020	
Date Inspected:	27/11/2020 Inspected At:	160 Sin Ming Drive #05-17 Sin Ming Autocity
		Repairer : Hiap Lek Automobile Trading
Estimated Period of Repair:	8.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*FRT BUMPER GRILLE	Broken	0.00 F	*- F
6	1		*FRT GRILLE	Cut	0.00 F	*- F
7	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
8	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
9	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
10	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
11	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
12	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
13	1		*REAR NUMBER PLATE BASE	Deformed	0.00 F	*- F
14	1		*REAR BUMPER	Cracked	0.00 F	*- F
15	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
16	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
17	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
18	1		*REAR BUMPER BEAM	Bent	0.00 F	*- F
19	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
20	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
21	1		*REAR END PANEL	Buckled	0.00 F	*- F
22	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
23	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
24	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
25	1		*BOOTLID	Repair	0.00 F	*- F
26	4		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
27	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
28	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F
29	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
30	1		*SPARE TYRE BOARD	Cut	0.00 F	*- F
31	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
32	1		*REAR LH FENDER INNER TRIM	Torn	0.00 F	*- F

F=Franchise part.

**Total Parts (\$\$)****0.00****0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**