

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20013075/APS3Q2  
**Date:** 25/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	GBB566A	<b>Insured Vehicle No :</b>	SH7142K
Date of Loss:	24/11/2020	Nature of Claim:	TP
		Claim No:	MCT20110406

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBB566A</b>		
Make & Model:	VOLKSWAGEN CADDY, 2.0 D (M)	Engine No:	BST061309
Reg. Date:	30/06/2008 (Man. Year: 2007)	Chassis No:	WV1ZZZ2KZ8X035469
Colour:	Yellow	Odometer:	136459 km
Engine Capacity:	1968 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,668.00	2,242.20	425.80	15.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,140.00	700.00	38.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,508.00</b>	<b>3,382.20</b>	<b>1,125.80</b>	<b>24.97</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		

<b>Nett Amount (S\$)</b>	<b>4,508.00</b>	<b>2,700.00</b>	<b>1,808.00</b>	<b>40.11</b>
<b>+ Car Rental (5.0 x S\$90.00/day) (S\$)</b>		450.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,157.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,150.00</b>		

INSPECTION

Date of Assignment: 26/11/2020

Date Inspected: 26/11/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Best Solution Autocare Pte Ltd (HQ)  
 53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK  
 Singapore 408934

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 22 Mar 2021)	
<b>Parts:</b>	N/A	VOLKSWAGEN CADDY 2.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBB566A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S FRONT FENDER	Dented	778.00 F	*778.00 FL
2	1		*O/S FRONT FENDER SIGNAL LAMP	Not Necessary	45.00 F	*- FL
3	1		*O/S FRONT DOOR	Dented	1,395.00 F	*1,395.00 FL
4	1		*O/S FRONT DOOR TOP HINGE	Not Necessary	115.00 F	*- FL
5	1		*O/S FRONT DOOR PROTECTOR	Cut	285.00 F	*285.00 FL
6	1		*BODY STICKER	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,668.00</b>	<b>2,488.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	245.80
<b>Total Parts (\$)</b>	<b>2,668.00</b>	<b>2,242.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE DAMAGED PARTS ,PANEL BEAT ,REPAIR	New	800.00	500.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	800.00	500.00
3	ANTI RUST	New	100.00	30.00
4	TRANSFER DOOR MECHANISM	New	80.00	80.00
5	WIRING CHECK	New	60.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,840.00</b>	<b>1,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >