

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20013079/EQD3E2

**Date:** 15/12/2020

### REFERENCE

Insured/Claimant:	NG HAI KIAT	Policy No:	1800049096	Claim No:	4573514486SG
Date of Loss:	29/10/2020	Nature of Claim:	OD		

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ5267K	Engine No:	G4FGJH695883
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAFX411MJ5765707
Reg. Date:	08/05/2018 (Man. Year: 2017)	Odometer:	19286 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$63,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55R15	Rear Tyre Size:	205/55R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,094.00	2,377.60	716.40	23.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	2,360.00	640.00	21.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,094.00</b>	<b>4,737.60</b>	<b>1,356.40</b>	<b>22.26</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>5,794.00</b>	<b>4,437.60</b>	<b>1,356.40</b>	<b>23.41</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>405.58</b>	<b>310.63</b>	<b>94.95</b>	<b>23.41</b>
<b>Nett Amount (S\$)</b>	<b>6,199.58</b>	<b>4,748.23</b>	<b>1,451.35</b>	<b>23.41</b>

### INSPECTION

Date of Assignment:	26/11/2020	
Date Inspected:	26/11/2020	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-FRONT DOOR,RH	Dented	1,542.00 FL	*1,542.00 FL
2	1		*COVER-FR DR O/S HDL,DRIVER	Not Necessary	22.00 FL	*- FL
3	1		*HANDLE ASSY-DOOR OUTSIDE	Not Necessary	58.00 FL	*- FL
4	1		*BASE ASSY-FR DR O/S HANDLE RH	Not Necessary	52.00 FL	*- FL
5	1		*LATCH ASSY-FRONT DOOR,RH	Not Necessary	253.00 FL	*- FL
6	1		*CHECKER ASSY-FRONT DOOR,RH	Not Necessary	32.00 FL	*- FL
7	1		*BLACK TAPE-FR DR FRAME UPR,RH	Necessary	13.00 FL	*13.00 FL
8	1		*BLACK TAPE-FR DR RR,RH	Necessary	12.00 FL	*12.00 FL
9	1		*PANEL ASSY-REAR DOOR,RH	Dented	1,361.00 FL	*1,361.00 FL
10	1		*COVER-FR DR O/S HDL,PASSENGER	Not Necessary	22.00 FL	*- FL
11	1		*HANDLE ASSY-DOOR OUTSIDE	Not Necessary	58.00 FL	*- FL
12	1		*BASE ASSY-FR DR O/S HANDLE RH	Not Necessary	52.00 FL	*- FL
13	1		*LATCH ASSY-REAR DOOR,RH	Not Necessary	309.00 FL	*- FL
14	1		*BLACK TAPE-RR DR FRAME UPR,RH	Necessary	11.00 FL	*11.00 FL
15	1		*TAPE-RR DR FRAME BLACK RR,RH	Necessary	8.00 FL	*8.00 FL
16	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,855.00	2,967.00
- List Item Discount on L Items 20.00/20.00% (\$)	761.00	589.40
Total Parts (\$)	3,094.00	2,377.60

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW ACCIDENT DAMAGED PARTS ON RH FRONT DOOR PANEL,RH REAR DOOR PANEL	New	1,200.00	800.00
2	REMOVE AND TRANSFER RH FRONT DOOR GLASS,TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL	New	120.00	120.00
3	PAINT WORK SPRAY RH FRONT DOOR PANEL,RH REAR DOOR PANEL AND AFFECTED PORTION	New	1,050.00	1,050.00
4	APPLY BODY SEALANT	New	120.00	80.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	PERFORM RUST PREVENTION	New	120.00	40.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	REMOVE AND TRANSFER RH REAR DOOR GLASS,TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL	New	120.00	120.00
9	TO CONDUCT COMPUTIREZE FULL WHEEL ALIGNMENT	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,000.00</b>	<b>2,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >