

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20013081/UQF3Q2

Date: 01/12/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MR005721

Claimant
Vehicle No : SHA6206J

Insured Vehicle No : SMV9404P

Date of Loss: 26/11/2020

Nature of Claim: TP

Claim No: M2005861

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA6206J**

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEKU211003

Reg. Date: 30/04/2019 (Man. Year: 2019)

Chassis No: KMHC851CVKU146253

Colour: Blue

Odometer: 211278 km

Engine Capacity: 1580 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,804.84	880.16	924.68	51.23
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	720.00	560.00	160.00	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,535.84	1,451.16	1,084.68	42.77
+ GST 7.00/7.00% (S\$)	177.51	101.58	75.93	42.78
Nett Amount (S\$)	2,713.35	1,552.74	1,160.61	42.77

INSPECTION

Date of Assignment: 26/11/2020 Present Location:

ComfortDelGro Engineering Pte Ltd
(Loyang)

Date Inspected: 27/11/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2020)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA6206J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed/Warped	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER CENTER MOULDING	Cracked	451.25 FL	-	*451.25 FL
3	1		*REAR BUMPER LOWER MOULDING	Repair	155.00 FL	-	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	-	*- FL
5	1		*REAR BUMPER REINFORCEMENT STAY LH	Not Necessary	138.10 FL	-	*- FL
6	1		*REAR BUMPER FOGLAMP	Not Necessary	201.50 FL	-	*- FL
7	1		*REAR BUMPER REFLECTOR LH	Not Necessary	41.45 FL	-	*- FL
8	1		*REAR BUMPER TOW COVER	Cut	98.80 FL	-	*98.80 FL
9	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
10	1		*REVERSE SENSOR	Serviceable	180.00 F	-	*- FS
11	1		*REAR NO.PLATE WITH TRIM COVER	Cracked	55.00 F	-	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,197.30	1,086.45
- List Item Discount on L Items 20.00/20.00% (\$\$)	392.46	206.29
Total Parts (\$\$)	1,804.84	880.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING	New	250.00	200.00
3	R/I REVERSE SENSOR	New	120.00	40.00
Gross Labour Cost (\$\$)			720.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >