

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20013100/ABA3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLM4398R	Insured Vehicle No :	SHD4774H
Date of Loss: 22/11/2020	Nature of Claim: TP	Claim No: MCT20110355

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM4398R		
Make & Model:	OPEL ASTRA, 1.4 HB (A)	Engine No:	B1162637GSGX0344
Reg. Date:	30/03/2017 (Man. Year: 2016)	Chassis No:	W0LBE6ECXHG023691
Colour:	Blue	Odometer:	54592 km
Engine Capacity:	1399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,800.90	1,449.90	5,351.00	78.68
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,580.00	890.00	1,690.00	65.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,391.90	2,350.90	7,041.00	74.97
+ GST 7.00/7.00% (\$\$)	657.44	164.56	492.88	74.97
Nett Amount (\$\$)	10,049.34	2,515.46	7,533.88	74.97
+ Loss of Use (6.0 x S\$80.00/day) (\$\$)		480.00		
Nett Liability (\$\$)		2,995.46		
Global Sum Settlement (\$\$)		2,850.00		

INSPECTION

Date of Assignment:	27/11/2020 Present Location:	ComfortDelGro Engineering Pte Ltd (Ubi)
Date Inspected:	30/11/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Ubi) 320 UBI ROAD 3 Singapore 408649
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Apr 2021)
Parts:	144	OPEL ASTRA 1.4 HB (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM4398R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Repair	1,560.00 F	*- F
2	1		*REAR TAIL GATE LOCK	Not Necessary	168.00 F	*- F
3	1		*ASTRA WORDING	Necessary	60.00 F	*60.00 F
4	1		*TURBO WORDING	Necessary	60.00 F	*60.00 F
5	1		*OPEL LOGO PLUS HANDLE	Not Necessary	132.00 F	*- F
6	1		*REAR BUMPER	Deformed	780.00 F	*780.00 F
7	15		*REAR BUMPER CLIPS	Necessary	2,700.00 F	*30.00 F
8	1		*REAR BUMPER RENFORCEMENT	Bent	384.00 F	*384.00 F
9	1		*REAR BUMPER SPONGE / BRACKET	Cracked	48.00 F	*48.00 F
10	1		*REAR BUMPER LOWER GARNISH	Deformed	204.00 F	*204.00 F
11	2		*REAR BUMPER REFLECTOR LAMP	Not Necessary	60.00 F	*- F
12	1		*REAR BUMPER TOW COVER	Not Necessary	54.00 F	*- F
13	1		*REAR END PANEL	Repair	384.00 F	*- F
14	2		*REAR REVERSE SENSOR (ORIGINAL)	Not Necessary	168.00 F	*- F
15	1		*NUMBER PLATE	Cracked	45.00 FS	*45.00 F
16	1		*SEALANT	Not Necessary	80.00 FS	*- FS
17	1		*INNER SEAL	Not Necessary	60.00 FS	*- FS
Supplementary #3						
18	1		*REAR BUMPER BRACKET LH	Not Necessary	45.00 F	*- F
19	1		*REAR BUMPER BRACKET RH	Not Necessary	45.00 F	*- F
20	1		*REAR BUMPER CENTER BRACKET	Not Necessary	65.00 F	*- F
21	1		*REAR BUMPER REINFORCEMENT	Not Necessary	384.00 F	*- F
22	10		*RIVET	Not Necessary	50.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	7,536.00	1,611.00
- Add. Disc. on L,N Items 10.00/10.00% (\$\$)	735.10	161.10
Total Parts (\$\$)	6,800.90	1,449.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer) (NECESSARY)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKET AND ETC	New	100.00	30.00
2	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	160.00	0.00
3	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	120.00	60.00
4	TO CUT & WELD REAR END PANEL , KNOCK AND REPAIR REAR SPARE TYRE PANEL AND AFFECTED AREA .	New	850.00	400.00
5	TO PUTTY & SPRAY PAINTING REAR TAIL GATE , REAR BUMPER , REAR END PANEL , REAR SPARE TYRE PANEL AND AFFECTED AREA	New	1,350.00	400.00
Gross Labour Cost (\$\$)			2,580.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >