Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013101/KBS3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070146532

Claimant
Vehicle No: Insured Vehicle No: SMV7346L

Date of Loss: 22/11/2020 Nature of Claim: TP Claim No: 2353502320SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGS7617S

Make & Model: MERCEDES-BENZ GLE250, 2.1 D 4MATIC (R18 Engine No: 27492030849133

LED) (A)

Reg. Date: 09/01/2017 (Man. Year: 2016) Chassis No: WDC2539462F173403

Colour: Metallic Dark Blue Odometer: 157926 km

Engine Capacity: 1991 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,419.00	5,080.30	4,338.70	46.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,290.00	1,500.00	53.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,209.00	6,370.30	5,838.70	47.82
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	12,209.00	5,100.00	7,109.00	58.23
+ Car Rental (4.0 x S\$13	30.00/day) (S\$)	520.00		
+ Doc/S	earch Fee (S\$)	7.45		
Net	tt Liability (S\$)	5,627.45		
Global Sum S	settlement (S\$)	5,600.00		

INSPECTION

Date of Assignment: 27/11/2020

Date Inspected: 30/11/2020 Inspected At: Lim Yew Boo Spray Paint Co (HQ)

Blk 10 Sin Ming Industrial Estate, #01-

10

Singapore 575645

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*REAR TAILGATE	Bent	2,912.00 F	*2,522.00 FN		
2	1		*REAR TAILGATE RUBBER	Serviceable	456.00 F	*- FN		
3	1		*REAR TAILGATE LOCK UPPER	Repair	321.00 F	*- FN		
4	1		*REAR TAILLAMP /LH	Cracked	609.00 F	*568.00 FN		
5	1		*REAR REFLECTOR LH	Serviceable	609.00 F	*- FN		
6	1		*REAR BUMPER	Buckled	975.00 F	*975.00 FN		
7	1		*REAR BUMPER -BLACK	Dented	567.00 F	*567.00 FN		
8	1		*REAR BUMPER CHROME	Scratched	517.00 F	*517.00 FN		
9	1		*REAR BUMPER RETAINER	N/S Distorted	304.00 F	*152.00 FN		
10	1		*REAR BUMPER REINFORCEMENT	Repair	827.00 F	*- FN		
11	1		*REAR EMBLEM 4MATIC	Necessary	107.00 F	*107.00 FN		
12	1		*REAR EMBLEM GLC 250	Necessary	103.00 F	*103.00 FN		
13	1		*REAR LID STAR	Necessary	53.00 F	*53.00 FN		
14	3		*REAR LID STAR CLIPS	Necessary	3.00 F	*3.00 FN		
15	3		*REAR REVERSE PDC SENSOR	Serviceable	936.00 F	*- FN		
16	1		*REAR W/SCREEN SEALANT	Necessary	60.00 FS	*40.00 FS		
17	1		*REAR W/SCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS		
F=Franchise part. S=SpcNett. N=NettItemDisc.								
				Sub Total (S\$)	9,419.00	5,637.00		
- Nett Item Discount on N Items 0.00/10.00% (S\$)				0.00	556.70			
				Total Parts (S\$)_	9,419.00	5,080.30		
Report was unsubmitted during this print-out.								

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=ge... 9/3/2021

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	New	120.00	30.00
2	TO REPLACE FRT SENSOR & CHECK SENSOR WIRING	New	120.00	60.00
3	LABOUR TO REMOVE /REFIX REAR SEAT ,INTERIOR GARNISH ,ETC	New	120.00	0.00
4	TO TRANSFER TAILGATE PARTS & FITTING TO NEW TAILGATE	New	80.00	60.00
5	LABOUR TO REMOVE /REFIX REAR W/SCREEN GLASS IN ORDER TO FACILITATE REPAIR JOBS	l New	150.00	120.00
6	TO CHECK WATER SEEPAGE	New	80.00	20.00
7	TO REPAIR ,REALIGN ON REAR EXHAUST SILENCER	New	120.00	0.00
8	TO REPAIR ,PANEL BEAT ON REAR AFFECTED TAILEND PANEL ,RE-STRAIGHTEN ON AFFECTED LEFT REAR FENDER & LABOUR TO REPLACED THE ABOVE PARTS	New	900.00	500.00
9	TO PUTTY ,PRIMER & SPRAY PAINT ON REAR TAILGATE ,REAR BUMPER ,TAILEND PANEL & TOUCH UP ON AFFECTED LEFT REAR FENDER USING 2K PAINT	New	1,100.00	500.00
	Gross Labour Cost (S\$)		2,790.00	1,290.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >