

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013105/BEA3Q2
Date: 12/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900244529
Claimant Vehicle No :	SGP9828C	Insured Vehicle No :	GBG3405K
Date of Loss:	26/11/2020	Nature of Claim:	TP
		Claim No:	7998010933SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGP9828C		
Make & Model:	MERCEDES-BENZ E200, 2.0 (A)	Engine No:	27492030771658
Reg. Date:	29/11/2016 (Man. Year: 2016)	Chassis No:	WDD2130422A076326
Colour:	Silver	Odometer:	41483 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,914.97	4,067.41	13,847.56	77.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	1,640.00	2,740.00	62.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,294.97	5,707.41	16,587.56	74.40
Approved Total (Overridden) (S\$)		4,550.00		

(S\$)	22,294.97	4,550.00	17,744.97	79.59
+ GST 7.00/7.00% (S\$)	1,560.65	318.50	1,242.15	79.59
Nett Amount (S\$)	23,855.62	4,868.50	18,987.12	79.59
+ Car Rental (7.0 x S\$140.00/day) (S\$)		980.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,855.95		

INSPECTION

Date of Assignment: 27/11/2020

Date Inspected: 27/11/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	2,399.00 FL	*- FL
2	1		*BOOTLID LOGO	Necessary	145.00 FL	*90.00 FL
3	1		*BOOTLID EMBLEM E200	Necessary	94.21 FL	*82.00 FL
4	1		*BOOTLID EMBLEM C&C	Necessary	68.00 FL	*45.00 FL
5	1		*BOOTLID EMBLEM 9G TRONIC	Necessary	94.21 FL	*65.00 FL
6	1		*BOOTLID OUTER CHROME MOULDING	Cut	168.00 FL	*168.00 FL
7	1		*BOOTLID INNER LOCK	Not Damaged	483.60 FL	*- FL
8	1		*BOOTLID WEATHERSTRIP	Not Damaged	295.60 FL	*- FL
9	1		*BOOTLID INNER TRIM BOARD	Not Damaged	983.60 FL	*- FL
10	2		*BOOTLID NUMBER PLATE LAMP	Not Damaged	176.46 FL	*- FL
11	1		*REAR BUMPER	Broken	2,044.00 FL	*1,590.00 FL
12	2		*REAR BUMPER RETAINER	Necessary	275.72 FL	*130.00 FL
13	1		*REAR BUMPER DIFFUSER	Cracked	583.36 FL	*300.00 FL
14	1		*REAR BUMPER DIFFUSER OUTER CHROME	Cut	168.00 FL	*168.00 FL
15	2		*REAR BUMPER REFLECTOR	Broken	136.68 FL	*136.68 FL
16	1		*REAR BUMPER REINFORCEMENT	Not Damaged	751.33 FL	*- FL
17	1		*REAR BUMPER BRACKET	No such part	101.82 FL	*- FL
18	6		*REVERSE SENSOR	Missing / Scratched (2 CSONLY)	1,470.00 FL	*360.00 FL
19	1		*REAR END PANEL	Not Damaged	1,752.30 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Not Damaged	347.74 FL	*- FL
21	1		*REAR FENDER LH	Repair	2,325.00 FL	*- FL
22	1		*REAR FENDER INNER TRIM BOARD LH	Not Damaged	325.00 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING	Not Damaged	254.00 FL	*- FL
24	2		*REAR EXHAUST CHROME MOULDING	Cut (1 PCS ONLY)	316.00 FL	*80.00 FL
25	2		*TAIL LAMP	Cut	1,788.00 FL	*1,138.00 FL
26	2		*TAIL LAMP LOWER BRACKET	No such part	370.00 FL	*- FL
27	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
28	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
29	1		*BOOTLID OUTER CHROME MOULDING CLIPS	Not Necessary	60.00 FS	*- FS
30	1		*BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
31	1		*REAR BUMPER CLIPS	Not Necessary	60.00 FS	*- FS
32	1		*REAR BUMPER DIFFUSER CLIPS	Necessary	60.00 FS	*30.00 FS
33	6		*REAR BUMPER REVERSE SENSOR SEAL	Necessary (2 PCS ONLY)	390.00 FS	*60.00 FS
34	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
35	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
37	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
38	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
39	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
40	1		*REAR WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
41	2		*TAILLAMP SEAL	Necessary	120.00 FS	*60.00 FS
42	2		*TAILLAMP CLIPS	Not Necessary	120.00 FS	*- FS
43	2		*REAR NUMBER PLATE W/CASING	Not Damaged	160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,706.63	4,502.68
- List Item Discount on L Items 10.00/10.00% (\$)	1,791.66	435.27
Total Parts (\$)	17,914.97	4,067.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BOOTLID COMPONENT	New	150.00	0.00
2	R&R REVERSE SENSOR	New	100.00	60.00
3	R&R REAR WINDSCREEN	New	250.00	0.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	150.00
5	UPHOLSTERY	New	300.00	0.00
6	CHECK WIRING	New	100.00	30.00
7	CONDUCT WATER LEAK TEST	New	180.00	0.00
8	PANEL BEAT	New	1,400.00	800.00
9	RUST PROOFING	New	200.00	0.00
10	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (S\$)			4,380.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >