

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20013110/EQF3E2  
**Date:** 15/12/2020

### REFERENCE

Insured/Claimant: LIM KAI ZHONG Policy No: 1800096523  
Date of Loss: 26/11/2020 Nature of Claim: OD Claim No: 0399954464SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF2116B**  
Make & Model: KIA CERATO K3, 1.6 (A) Engine No: G4FGJH703409  
Reg. Date: 13/08/2018 (Man. Year: 2018) Chassis No: KNAF3416MK5013256  
Colour: Grey Odometer: 78815 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: S\$65,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,171.20	2,534.40	3,636.80	58.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,670.00	3,310.00	1,360.00	29.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,841.20</b>	<b>5,844.40</b>	<b>4,996.80</b>	<b>46.09</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>758.88</b>	<b>409.11</b>	<b>349.77</b>	<b>46.09</b>
<b>Nett Amount (S\$)</b>	<b>11,600.08</b>	<b>6,253.51</b>	<b>5,346.57</b>	<b>46.09</b>

### INSPECTION

Date of Assignment: 27/11/2020  
Date Inspected: 27/11/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339  
Estimated Period of Repair: 6.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*W/STRIP-TRUNK LID OPNG	Not Necessary	100.00 FL	*- FL
2	1		*LATCH ASSY-TRUNK LID	Not Necessary	112.00 FL	*- FL
3	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 FL	*- FL
4	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
5	1		*TRIM ASSY-RR TRANSVERSE	Not Necessary	41.00 FL	*- FL
6	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
7	1		*HINGE ASSY-TRUNK LID,RH	Not Necessary	97.00 FL	*- FL
8	1		*HINGE ASSY-TRUNK LID,LH	Not Necessary	97.00 FL	*- FL
9	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
10	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
11	1		*LAMP ASSY-CENTER GARNISH	Not Necessary	690.00 FL	*- FL
12	1		*LAMP ASSY-REAR COMB INSIDE,LH	Not Necessary	608.00 FL	*- FL
13	1		*LAMP ASSY-REAR COMB INSIDE,RH	Not Necessary	608.00 FL	*- FL
14	1		*LAMP ASSY-REAR COMB OUTSIDE,LH	Not Necessary	675.00 FL	*- FL
15	1		*LAMP ASSY-REAR COMB OUTSIDE,RH	Not Necessary	675.00 FL	*- FL
16	1		*BRACKET ASSY-RR BPR SIDE UPR,L	Broken	25.00 FL	*25.00 FL
17	1		*BRACKET ASSY-RR BPR SIDE UPR,R	Broken	31.00 FL	*31.00 FL
18	1		*COVER-RR BUMPER UNDER,RH	Not Necessary	33.00 FL	*- FL
19	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
20	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
21	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
22	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
23	1		*BRACKET-RR BEAM UPR MTG,LH	Not Necessary	9.00 FL	*- FL
24	1		*BRACKET-RR BEAM UPR MTG,RH	Not Necessary	9.00 FL	*- FL
25	1		*BRACKET-RR BEAM LWR,CTR	Not Necessary	6.00 FL	*- FL
26	2		*BRACKET-RR BEAM LWR,MTG	Not Necessary	12.00 FL	*- FL
27	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FL	*- FL
28	1		*LAMP ASSY-SIDE T/SIGNAL,LH	Not Necessary	181.00 FL	*- FL
29	1		*LAMP ASSY-SIDE T/SIGNAL,RH	Not Necessary	181.00 FL	*- FL
30	1		*COVER-RR BUMPER FOG LAMP,LH	Not Necessary	19.00 FL	*- FL
31	1		*COVER-RR BUMPER FOG LAMP,RH	Cut	19.00 FL	*19.00 FL
32	10		*CLIP	Necessary	10.00 FL	*10.00 FL
33	2		*GROMMET ASSY-SCREW	Necessary	4.00 FL	*4.00 FL
34	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
35	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
36	1		*COVER-RR BUMPER UNDER,LH	Broken	33.00 FL	*33.00 FL
37	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
38	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,689.00</b>	<b>3,163.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	1,517.80	628.60
<b>Total Parts (S\$)</b>	<b>6,171.20</b>	<b>2,534.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID.REAR BUMPER,CUT/WELD REAR END PANEL,REPAIR RH REAR FENDER	New	2,000.00	1,400.00
2	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
3	REMOVE AND INSTALL REAR CABIN AND OTHERS ATTACHMENT TO FACILITATE REPAIR WORK	New	120.00	120.00
4	PAINT WORK SPRAY REAR END PANEL,REAR BUMPER,REAR BOOT LID,RH REAR FENDER,LH REAR FENDER AND AFFECTED PORTION	New	2,100.00	1,400.00
5	SUPPLY C&C LOGO	New	40.00	40.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	APPLY BODY SEALANT	New	120.00	80.00
9	PERFORM RUST PREVENTION	New	80.00	60.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >