

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 30 Nov 2020

**Preliminary Advice**

Vehicle No	: SJN9695T	Accident Date	: 23/11/2020
Make	: TOYOTA AXIO	Policy No.	: DMHCSNA00006592000
Assignment Date	: 27/11/2020	Excess	: S\$500.00
Date of Inspection	: 27/11/2020	Est. Duration of Repair	: 10
Inspection At	: Kt Garage Pte Ltd (HQ) BLK 1 KAKI BUKIT AVENUE 6 #01-04, AUTO BAY@KAKI BUKIT ENTRANCE A Singapore 417883		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,284.40
Revised Amount	:S\$	6,253.60
Check Items (Estimated)	:S\$	1,935.50
Total	:S\$	8,189.10

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	15,000.00
COE / PARF Rebate	:S\$	8,344.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,656.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer able to undertake the repair cost not exceeding L/S \$6,000.00.