

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20013115/EQF3E2
Date: 13/01/2021

REFERENCE

Insured/Claimant: WONG DAWEI, KELVIN Policy No: 1900083554
Date of Loss: 27/11/2020 Nature of Claim: OD Claim No: 8751683185SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK4652E**
Make & Model: KIA CERATO, 1.6 EX (A) Engine No: G4FGJH723726
Reg. Date: 11/04/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5032049
Colour: Blue Odometer: 26385 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,758.00	8,250.40	3,507.60	29.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,280.00	7,895.00	3,385.00	30.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,038.00	16,145.40	6,892.60	29.92
+ GST 7.00/7.00% (S\$)	1,612.66	1,130.18	482.48	29.92
Nett Amount (S\$)	24,650.66	17,275.58	7,375.08	29.92

INSPECTION

Date of Assignment: 27/11/2020
Date Inspected: 27/11/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 14.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Not Necessary	1,219.00 FL	*- FL
3	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Cut	675.00 FL	*675.00 FL
4	1		*LAMP ASSY-REAR COMB INSIDE, RH	Cut	608.00 FL	*608.00 FL
5	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Cracked	675.00 FL	*675.00 FL
6	1		*LAMP ASSY-REAR COMB INSIDE, LH	Cracked	608.00 FL	*608.00 FL
7	1		*LAMP ASSY-CENTER GARNISH	Not Necessary	690.00 FL	*- FL
8	1		*PANEL ASSY-REAR FLOOR, RR	Dented	219.00 FL	*219.00 FL
9	1		*PANEL ASSY-QUARTER OUTER, LH	Dented	1,349.00 FL	*1,349.00 FL
10	1		*PANEL ASSY-RR COMB LAMP HSG, LH	Dented	139.00 FL	*139.00 FL
11	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
12	1		*HINGE ASSY-TRUNK LID, LH	Not Necessary	97.00 FL	*- FL
13	1		*HINGE ASSY-TRUNK LID, RH	Not Necessary	97.00 FL	*- FL
14	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
15	1		*PANEL & FRAME ASSY-PKG TRAY, RR	Not Necessary	312.00 FL	*- FL
16	1		*TRIM ASSY-RR TRANSVERSE	Crushed	41.00 FL	*41.00 FL
17	1		*MAT ASSY-LUGGAGE COVERING	Broken	211.00 FL	*211.00 FL
18	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 FL	*100.00 FL
19	1		*TRIM ASSY-TRUNK LID	Crushed	202.00 FL	*202.00 FL
20	1		*LATCH ASSY-TRUNK LID	Bent	112.00 FL	*112.00 FL
21	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 FL	*- FL
22	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
23	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
24	1		*GRILLE-FRONT BUMPER	Cut	262.00 FL	*262.00 FL
25	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
26	1		*LAMP ASSY-SIDE REPEATER, LH	Not Necessary	143.00 FL	*- FL
27	1		*MOULDING-FRONT BUMPER, LH	Not Necessary	36.00 FL	*- FL
28	1		*AIR DUCT-FR BUMPER, LH	Broken	14.00 FL	*14.00 FL
29	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
30	1		*GUARD- REAR WHEEL, LH	Not Necessary	75.00 FL	*- FL
31	1		*GLASS ASSY-REAR WINDOW	Not Necessary	447.00 FL	*- FL
32	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
33	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
34	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
35	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
36	1		*COVER-RR BUMPER LWR (5PCS)	Broken (1pc only)	1,205.00 FL	*241.00 FL
37	1		*COVER-RR BUMPER UNDER, LH	Crushed	33.00 FL	*33.00 FL
38	1		*COVER-RR BUMPER FOG LAMP, LH	Broken	19.00 FL	*19.00 FL
39	1		*COVER-RR BUMPER FOG LAMP, RH	Not Necessary	19.00 FL	*- FL
40	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Broken	181.00 FL	*181.00 FL
41	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 FL	*- FL
42	1		*BRACKET-RR BEAM UPR MTG, LH	Broken	9.00 FL	*9.00 FL
43	1		*BRACKET-RR BEAM UPR MTG, RH	Broken	9.00 FL	*9.00 FL
44	1		*BRACKET-RR BEAM LWR, CTR	Broken	6.00 FL	*6.00 FL
45	1		*BRACKET-RR BEAM LWR MTG	Broken	6.00 FL	*6.00 FL
46	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
47	1		*ANTENNA ASSY-SMARTKEY	Broken	46.00 FL	*41.00 FL
48	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
49	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
50	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Broken	25.00 FL	*25.00 FL
51	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Broken	31.00 FL	*31.00 FL
52	1		*REINF-TOWING HOOK (Supplementary)	Necessary	14.00 FL	*14.00 FL
53	6		*FASTENER (Supplementary)	Necessary	6.00 FL	*6.00 FL
54	1		*EXTN WIRING ASSY -BWS (Supplementary)	Broken	207.00 FL	*207.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*GLASS & MOULDING ASSY - QUARTER (Supplementary)	Necessary	252.00 FL	*252.00 FL
56	1		*BRACKET ASSY - SPARE TIRE MTG (Supplementary)	Necessary	15.00 FL	*15.00 FL
57	1		*HOOK - TOWING (Supplementary)	Necessary	16.00 FL	*16.00 FL
58	2		*GROMMET ASSY - SCREW (Supplementary)	Necessary	4.00 FL	*4.00 FL
59	1		*REINF -RR SPARE TIRE WELL CROSS (Supplementary)	Necessary	41.00 FL	*41.00 FL
60	1		*SILENCER, FLOOR (Supplementary)	Necessary	13.00 FL	*13.00 FL
61	20		*CLIP (Supplementary)	Necessary	20.00 FL	*20.00 FL
62	1		*FILM -ANTI CHIPPG LH (Supplementary)	Necessary	27.00 FL	*27.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,685.00	10,308.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,927.00	2,057.60
Total Parts (\$\$)	11,758.00	8,250.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER & AFFECTED AREA. REPAIR ON FRT LH FENDER	New	1,200.00	400.00
2	REPLACE REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, REAR LH FENDER, REAR LH TAIL LAMP PANEL & AFFECTED AREA. REPAIR ON REAR RH FENDER	New	4,000.00	2,200.00
3	PAINT WORK ON FRT BUMPER & FRT LH FENDER	New	700.00	700.00
4	PAINT WORK ON REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, REAR LH TAIL LAMP PANEL & BOTH REAR FENDER	New	2,450.00	1,925.00
5	REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR	New	120.00	120.00
6	REMOVE & INSTALL REAR BOOT COMPONENTS TO FACILITATE REPAIR	New	120.00	120.00
7	REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR, AND CONDUCT WATER LEAK TEST	New	240.00	240.00
8	APPLY REAR WINDSCREEN GLASS SEALANT	New	80.00	80.00
9	REMOVE & INSTALL REAR SEAT COMPARTMENTS TO FACILITATE REPAIR	New	120.00	120.00
10	TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL	New	120.00	80.00
11	APPLY BODY SEALANT ON AFFECTED AREA	New	120.00	80.00
12	PERFORM RUST PREVENTION	New	160.00	80.00
13	SUPPLY C&C EMBLEM	New	40.00	40.00
14	APPLY ANTI-CORROSION	New	40.00	40.00
15	R&I FUEL TANK	New	400.00	400.00
16	TO SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
17	TO SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	50.00
18	REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR (NPA)(Repeated)	New	0.00	0.00
19	CUT & WELD AND REPLACE REAR FLOOR PANEL (Supplementary)	New	900.00	800.00
20	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM (Supplementary)	New	30.00	30.00
21	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST (Supplementary)	New	120.00	120.00
22	SUPPLY REVERSE SENSOR (Supplementary)	New	220.00	220.00
Gross Labour Cost (\$\$)			11,280.00	7,895.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >