

ASS. REC. BY:

Steve

REF:

CS/AIG 20013115/ERF3

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

1900083554

Claims No.

8751683185SG

Sum Insured:


Excess:

0/-

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.


Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMK 4652E

Yr Regn:

11/4/19

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c 1591

Colour:

Blue

A/C: Insured / Std / NI / N

Sp. Reading

26385

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNIAF 3416 MK 503249

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

11

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

97/11/20

D.O.A.

27/11/20

Survey held at

cycle & camp

Des. of Damages ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV- 70K

27/11/20@5.58pm revert to AIG via Merimen.

30/11/20@6.47pm Lois Chang informed C/A via Merimen.

01/12/20@9.24am Informed Kevin C/A & ex \$0/- by email.

07/01/21@11.15am Confirmed with Larry final fig \$16,145.40, 14 repair days. (Red \$6892.60, 30%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

14

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

S + RS, SI

Phone

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Form:

MER-OD

Total Sum / L.E.:

16145.40



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV09269/WONG DAWEI, KELVIN Reg No/Reg Date SMK4652E / 11/04/201 Date In/Mileage 27/11/2020/ 0 Chassis No KNAF3416MK5032049 Engine No G4FGJH723726 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	27/11/2020/ 14:12	QUK	282 / Kevin Leong	24935		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1200.00
REPLACE FRT BUMPER & AFFECTED AREA 400							
REPAIR ON FRT LH FENDER.							
E PNT88000							4000.00
REPLACE REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, REAR LH FENDER, 400							
REAR LH TAIL LAMP PANEL & AFFECTED AREA							
REPAIR ON REAR RH FENDER X							
E PNT98000							700.00
PAINT WORK ON FRT BUMPER & FRT LH FENDER 350							
E PNT98000							2450.00
PAINT WORK ON REAR BUMPER, BOOT, END PANEL, FLOOR PANEL,							
REAR LH TAIL LAMP PANEL & BOTH REAR FENDER							
E PNT88000							120.00
REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR							
E PNT88000							120.00
REMOVE & INSTALL REAR BOOT COMPONENTS TO FACILITATE REPAIR							
E PNT88000							240.00
REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR, AND							
CONDUCT WATER LEAK TEST							
M SUNDRY							80.00
APPLY REAR WINDSCREEN GLASS SEALANT							
E PNT88000							120.00
REMOVE & INSTALL REAR SEAT COMPARTMENTS TO FACILITATE REPAIR (photo)							
E PNT88000							120.00
TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL							
M SUNDRY							120.00
APPLY BODY SEALANT ON AFFECTED AREA							
M SUNDRY							160.00
PERFORM RUST PREVENTION							
M SUNDRY							40.00
SUPPLY C & C EMBLEM							
M SUNDRY							40.00
APPLY ANTI-CORROSION							
* R&I fuel tank							
							\$400

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #08-16
AIG BUILDING
SINGAPORE 079120
Contact No 64191000

Owner Name & Vehicle Info

Cust No/Name LCV09269/WONG DAWEI, KELVIN
Reg No/Reg Date SMK4652E / 11/04/201
Date In/Mileage 27/11/2020/ 0
Chassis No KNAF3416MK5032049
Engine No G4FGJH723726
Make/Model KIA/CERATO 1.6 A EX G333
Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	27/11/2020/ 14:12	QUK	282 / Kevin Leong	24935			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								50.00
TO SUPPLY FRONT NUMBER PLATE WITH FRAME								50.00
M SUNDRY								20 50.00
TO SUPPLY REAR NUMBER PLATE WITH FRAME								
M SUNDRY								
SUNDRIES					1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD,LH					1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE,RH					1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE,RH					1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE,LH					1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE,LH					1.00	690.00	20.00	552.00
M LAMP ASSY-CENTER GARNISH					1.00	219.00	20.00	175.20
M PANEL ASSY-REAR FLOOR,RR					1.00	1349.00	20.00	1079.20
M PANEL ASSY-QUARTER OUTER,LH					1.00	139.00	20.00	111.20
M PANEL ASSY-RR COMB LAMP HSG,LH					1.00	1297.00	20.00	1037.60
M PANEL ASSY-TRUNK LID					1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID,LH					1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID,RH					1.00	324.00	20.00	259.20
M PANEL ASSY-BACK					1.00	312.00	20.00	249.60
M PANEL & FRAME ASSY-PKG TRAY,RR					1.00	41.00	20.00	32.80
M TRIM ASSY-RR TRANSVERSE					1.00	211.00	20.00	168.80
M MAT ASSY-LUGGAGE COVERING					1.00	100.00	20.00	80.00
M W/STRIP-TRUNK LID OPNG					1.00	202.00	20.00	161.60
M TRIM ASSY-TRUNK LID					1.00	112.00	20.00	89.60
M LATCH ASSY-TRUNK LID					1.00	40.00	20.00	32.00
M STRIKER ASSY-TRUNK LID X					1.00	633.00	20.00	506.40
M COVER-FR BUMPER					1.00	328.00	20.00	262.40
M GRILLE ASSY-RADIATOR					1.00	262.00	20.00	209.60
M GRILLE-FRONT BUMPER					1.00	84.00	20.00	67.20
M ABSORBER-FRONT BUMPER ENERGY					1.00	143.00	20.00	114.40
M LAMP ASSY-SIDE REPEATER,LH					1.00	36.00	20.00	28.80
M MOULDING-FRONT BUMPER,LH					1.00	14.00	20.00	11.20
M AIR DUCT-FR BUMPER,LH								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>LCV09269/WONG DAWEI, KELVIN</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMK4652E / 11/04/201</td></tr> <tr> <td>Date In/Mileage</td><td>27/11/2020/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5032049</td></tr> <tr> <td>Engine No</td><td>G4FGJH723726</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>B4U GRAVITY BLUE / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV09269/WONG DAWEI, KELVIN	Reg No/Reg Date	SMK4652E / 11/04/201	Date In/Mileage	27/11/2020/ 0	Chassis No	KNAF3416MK5032049	Engine No	G4FGJH723726	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK
Cust No/Name	LCV09269/WONG DAWEI, KELVIN														
Reg No/Reg Date	SMK4652E / 11/04/201														
Date In/Mileage	27/11/2020/ 0														
Chassis No	KNAF3416MK5032049														
Engine No	G4FGJH723726														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	27/11/2020/ 14:12	QUK	282 / Kevin Leong	24935			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET-FR BUMPER UPR SIDE MTG	1			1.00	22.00	20.00	17.60
M	GUARD-REAR WHEEL, LH				1.00	75.00	20.00	60.00
M	GLASS ASSY-REAR WINDOW	X			1.00	447.00	20.00	357.60
M	ORNAMENT-KIA NO.115	NR			1.00	32.00	20.00	25.60
M	EMBLEM-CERATO	NR			1.00	28.00	20.00	22.40
M	LOGO ASSY-KIA SUB	NR			1.00	32.00	20.00	25.60
M	COVER-RR BUMPER	BR			1.00	651.00	20.00	520.80
M	COVER-RR BUMPER LWR	BR			5.00	241.00	20.00	964.00
M	COVER-RR BUMPER UNDER, LH	CRU			1.00	33.00	20.00	26.40
M	COVER-RR BUMPER FOG LAMP, LH	BR			1.00	19.00	20.00	15.20
M	COVER-RR BUMPER FOG LAMP, RH	BR			1.00	19.00	20.00	15.20
M	LAMP ASSY-SIDE T/SIGNAL, LH	BR			1.00	181.00	20.00	144.80
M	LAMP ASSY-SIDE T/SIGNAL, RH	BR			1.00	181.00	20.00	144.80
M	BRACKET-RR BEAM UPR MTG, LH	BR			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG, RH	BR			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM LWR, CTR	BR			1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM LWR MTG	BR			1.00	6.00	20.00	4.80
M	BEAM-RR BUMPER	BR			1.00	318.00	20.00	254.40
M	ANTENNA ASSY-SMARTKEY	?			1.00	46.00	20.00	36.80
M	STAY-RR BUMPER LH	BT			1.00	65.00	20.00	52.00
M	STAY-RR BUMPER RH	BT			1.00	65.00	20.00	52.00
M	BRACKET ASSY-RR BPR SIDE UPR, L	BR			1.00	25.00	20.00	20.00
M	BRACKET-ASSY RR BPR SIDE UPR, R	BR			1.00	31.00	20.00	24.80

Estimate

Steve (LKK) DD - Abt Authn
Excess - ?
27/11/20, 3:00pm
P/P, My Bel sm

Steve (LKK) 90-161 Author
EXCESS - ?
27/11/20, 3:00pm
P/P, My Bel SM
14 days

LKK Auto Consultants hereby confirm & accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work must be authorized and approved by the repairer

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Nett	20,876.00
7% GST on	1461.32
Total Payable	22,337.32