



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2100205

INV Date 12/01/2021

Reference CC4/LPC20013118/Kba3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMV 1278P
Insured Veh. YP 8899R
Claim No. 20/20/20/VC05/023941
Policy No. Z20VC05004379
Accident Date 25/11/2020
Inspection Date 27/11/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20013118/Kba3q2	Date: 12/01/2021
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 8899R	Veh. Inspected	SMV 1278P	
Policy No.	Z20VC05004379	Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023941	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	27/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC300	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	W1N2533842F836695	Colour	METALLIC RED	
Odometer	4961 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R19	MICHELIN	9 mm	
L/H Front Tyre	235/55 R19	MICHELIN	9 mm	
R/H Rear Tyre	255/50 R19	MICHELIN	9 mm	
L/H Rear Tyre	255/50 R19	MICHELIN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/11/2020	Inspection Date	27/11/2020	
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 1278P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE (N)	BENT	3,085.00	3,085.00
1	TAILGATE REFLECTOR -RH/LH @\$540.00 (N)	CUT / CRACKED	1,080.00	1,080.00
1	TAILGATE TRIMBOARD (N)	DENTED	450.00	450.00
2	TAILGATE HINGES -RH/LH @\$193.00 (N)	TO REPAIR SEE LABOUR	386.00	-
1	TAILGATE LOCK (N)	TO REPAIR SEE LABOUR	320.00	-
1	TAILGATE WEATHERSTRIP (N)	SERVICEABLE	1,000.00	-
1	TAILGATE CENTRE LOGO (N)	NECESSARY	170.00	170.00
1	TAILGATE 'GLC300' EMBLEM (N)	NECESSARY	128.00	128.00
1	TAILGATE '4 MATIC' EMBLEM (N)	NECESSARY	122.00	122.00
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	1,840.00	-
1	REAR END PANEL TOP GARNISH (N)	SERVICEABLE	368.00	-
1	REAR BUMPER (UPPER) (N)	BUCKLED / DENTED	1,350.00	1,350.00
1	REAR BUMPER (LOWER) (N)	BENT	775.00	775.00
1	REAR BUMPER LOWER CHROME (CENTER) (N)	CRACKED	168.00	168.00
2	REAR BUMPER LOWER CHROME -RH/LH @\$190.00 (N)	SERVICEABLE	380.00	-
1	REAR BUMPER REINFORCEMENT (N)	BUCKLED	795.00	795.00
2	REAR BUMPER SENSOR @\$190.00 (N)	SHORTED (1 PCS ONLY)	380.00	190.00
6	REAR BUMPER SENSOR SEALS @\$12.00 (N)	NECESSARY	72.00	72.00
1	REAR BUMPER SPONGE (N)	CRACKED	160.00	160.00
	LESS 10% DISCOUNT		-1,302.90	-854.50
			11,726.10	7,690.50
15	TAILGATE TRIMBOARD CLIPS @\$12.00 (SN)	NECESSARY	180.00	50.00
15	REAR BUMPER CLIPS @\$9.00 (SN)	NECESSARY	135.00	50.00
	LESS 10% DISCOUNT		-31.50	-
			283.50	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	TAILGATE 'C&C' EMBLEM (SN)	NECESSARY	38.00	38.00
1	REAR NUMBER PLATE (SN)	DENTED	40.00	40.00
			138.00	118.00
	<u>LABOUR</u>			
	TO TRANSFER DAMAGED TAILGATE INTERIOR MECHANISM TO NEW TAILGATE .		120.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS .		150.00	120.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR .		100.00	60.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PANEL BEAT AND STRAIGHTEN REAR FLOORBOARD PANEL ,REAR CHASSIS FRAME ,TO CUT AND WELD REAR END PANEL,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME.INCLUSIVE OF THE REPAIR OF TAILGATE HINGES -RH/LH,TAILGATE LOCK AND REAR END PANEL.		1,200.00	500.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.		1,200.00	600.00
	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS.		120.00	30.00
			2,970.00	1,390.00
GRAND TOTAL			15,117.60	9,298.50
RECOMMENDED COST OF REPAIRS				9,298.50

Report Ref No. CC4/LPC20013118/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMV 1278P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMV 1278P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMV 1278P

RE-INSPECTION

