

ASS. REC. BY:

REF:

UPC / 200131181K6

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 1.8 / % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMV 1278P Yr Regn: 10, 20Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mer GLC 300 c.c. 1991Colour: M. Red A/C: Insured / Std / NI / NASp. Reading: 4.961 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WIN 25338 42F 838095Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD A/Rlm orTyre Size: F: 235/55R19R: 255/50R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 25/11/20D.O.I. 27/11/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/12 @ 928.50 Car frame

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI _____

Fees _____

Others _____

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : YP8899R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 25/11/2020

TP VEH REG NO : YP8899R

ESTIMATE

NO : QUOT202011-000081(00)

DATE : 27/11/2020

POLICY NO : 999995580

VEH REG NO : SMV1278P

MAKE/MODEL : MERCEDES BENZ GLC300
4MATIC COUPE (R19 LED)

CHASSIS NO : W1N2533842F836695

ENGINE NO : 26492080074066

REG. DATE : 2020

Not Authorized
Running B4 painting

9,298.50 5 days

Estimate Repair Cost to Vehicle No : SMV1278P

Description	Quantity	Unit Price	Amount
		SS	SS
NET PRICE			
1 Tailgate	1	3,085.00	3,085.00
2 Tailgate reflector - RH / LH	2	540.00	1,080.00
3 Tailgate trimboard	1	450.00	450.00
4 Tailgate trimboard clips	15	12.00	180.00
5 Tailgate hinges - RH / LH	2	193.00	386.00
6 Tailgate lock	1	320.00	320.00
7 Tailgate weathertrip	1	1,000.00	1,000.00
8 Tailgate centre logo	1	170.00	170.00
9 Tailgate 'GLC300' emblem	1	128.00	128.00
10 Tailgate '4 MATIC' emblem	1	122.00	122.00
11 Rear end panel	1	1,840.00	1,840.00
12 Rear end panel top garnish	1	368.00	368.00
13 Rear bumper (upper)	1	1,350.00	1,350.00
14 Rear bumper (lower)	1	775.00	775.00
15 Rear bumper lower chrome (center)	1	168.00	168.00
16 Rear bumper lower chrome - RH / LH	2	190.00	380.00
17 Rear bumper reinforcement	1	795.00	795.00
18 Rear bumper sensor	1	190.00	190.00
19 Rear bumper sensor seals	6	12.00	72.00
20 Rear bumper clips	15	9.00	135.00
			13,184.00
		Less 10%	1,318.40
			11,865.60
SPECIAL NET			
21 Rear windscreen sealant	1	60.00	60.00
22 Tailgate 'C & C' emblem	1	38.00	38.00
23 Rear number plate	1	40.00	40.00
			138.00
LABOUR			
24 To transfer damaged tailgate interior mechanism to new tailgate	1	120.00	120.00
25 To remove and refit rear windscreen glass	1	150.00	150.00
26 To remove and refit rear bumper sensor	1	100.00	100.00
27 To check and rectify wiring system	1	80.00	80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : YP8899R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 25/11/2020

TP VEH REG NO : YP8899R

ESTIMATE

NO : QUOT202011-000081(00)
DATE : 27/11/2020
POLICY NO : 999995580
VEH REG NO : SMV1278P
MAKE/MODEL : MERCEDES BENZ GLC300
4MATIC COUPE (R19 LED)
CHASSIS NO : W1N2533842F836695
ENGINE NO : 26492080074066
REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SMV1278P

Description	Quantity	Unit Price	Amount	
			S\$	S\$
28 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00	500
29 To putty and spray paint on affected areas	1	1,200.00	1,200.00	600
30 To apply rust-proofing on replaced and repaired panels.	1	120.00	120.00	30
			2,970.00	
TOTAL			S\$ 14,973.60	
ADD GST @ 7%			1,048.15	
GRAND TOTAL			S\$ 16,021.75	

SINGAPORE DOLLAR SIXTEEN THOUSAND TWENTY-ONE AND CENTS SEVENTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE