

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT120013119/BTD3E2
Date: 30/12/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00109242000	
Claimant Vehicle No :	SLT2651K	Insured Vehicle No :	XE5940T	
Date of Loss:	21/11/2020	Nature of Claim:	TP	Claim No: SNM20D204604/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT2651K		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZR0A04356
Reg. Date:	24/10/2017 (Man. Year: 2017)	Chassis No:	ZVW400026597
Colour:	White	Odometer:	210009 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 5 mm	Rear Left Side:	Goodride 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Goodride 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,885.32	1,901.22	4,984.10	72.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,450.00	2,080.00	2,370.00	53.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,335.32	3,981.22	7,354.10	64.88
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	11,335.32	3,200.00	8,135.32	71.77

INSPECTION

Date of Assignment:	27/11/2020		Team Autopro Pte Ltd (Sin Ming)
Date Inspected:	27/11/2020	Inspected At:	160 SIN MING DR
Estimated Period of Repair:	7.0 days		#01-14 SIN MING AUTO CITY
			SINGAPORE 575722

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2020)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT2651K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	532.90 FL	*489.30 FL
2	2		*REAR BUMPER RETAINER	Necessary	189.60 FL	*125.40 FL
3	1		*REAR BUMPER REFLECTOR	Not Damaged	81.70 FL	*- FL
4	1		*REAR END PANEL	Not Damaged	602.10 FL	*- FL
5	1		*REAR FENDER RH	Dented	620.00 FL	*620.00 FL
6	1		*REAR FENDER INNER TRIM BOARD RH	Not Damaged	523.00 FL	*- FL
7	1		*REAR FENDER INNER COWLING RH	Not Damaged	286.30 FL	*- FL
8	1		*REAR FENDER SIDE GLASS MOULDING RH	Necessary	180.00 FL	*76.00 FL
9	1		*REAR AIR VENTS RH	Not Damaged	78.00 FL	*- FL
10	1		*REAR DOOR RH	Repair	914.00 FL	*- FL
11	1		*REAR DOOR INNER LOCK RH	Not Damaged	224.00 FL	*- FL
12	1		*SIDE SKIRT RH	Repair	458.00 FL	*- FL
13	1		*TAIL LAMP RH	Broken	624.40 FL	*486.00 FL
14	1		*TAIL LAMP LOWER BRACKET RH	No such part	36.70 FL	*- FL
15	1		*REAR AXLE	Not Damaged	686.00 FL	*- FL
16	1		*REAR WHEEL BEARING RH	Jammed	351.60 FL	*351.60 FL
17	1		*REAR SHOCK ABSORBER RH	Not Damaged	298.80 FL	*- FL
18	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
19	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
21	1		*FENDER SEALANT	Not Necessary	100.00 FS	*- FS
22	1		*FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*REAR FENDER SIDE GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
25	1		*REAR FENDER SIDE GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
26	1		*REAR FENDER SIDE GLASS PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
27	1		*REAR DOOR CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*SIDE SKIRT CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*TAILLAMP SEAL	Necessary	60.00 FS	*20.00 FS
30	1		*TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*REAR RIM	Not Damaged	450.00 FS	*- FS
32	1		*REAR RIM CAP	Cut	200.00 FS	*200.00 FS
33	1		*REAR TYRE	Not Damaged	380.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					8,557.10	2,438.30
- List Item Discount on L Items 25.00/25.00% (\$)					1,671.78	537.08
Total Parts (\$)					6,885.32	1,901.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REVERSE SENSOR	New	100.00	60.00
2	R&R REAR FENDER SIDE GLASS	New	250.00	80.00
3	R&R REAR DOOR COMPONENT	New	150.00	0.00
4	R&R REAR UNDER CARRIAGE	New	300.00	80.00
5	R&R REAR TYRE & BALANCING	New	100.00	0.00
6	WHEEL ALIGNMENT	New	150.00	60.00
7	UPHOLSTERY	New	300.00	0.00
8	CHECK WIRING	New	100.00	0.00
9	PANEL BEAT	New	1,400.00	1,000.00
10	RUST PROOFING	New	200.00	0.00
11	SPRAY PAINTING	New	1,400.00	800.00
Gross Labour Cost (\$\$)			4,450.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >