

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013122/BES3Q2
Date: 08/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100152365
Claimant Vehicle No :	SLW6757Y	Insured Vehicle No :	GBB6140E
Date of Loss:	23/09/2020	Nature of Claim:	TP
		Claim No:	7938790798SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW6757Y		
Make & Model:	MERCEDES-BENZ E220, 2.0 (A)	Engine No:	65492080032372
Reg. Date:	20/10/2016 (Man. Year: 2016)	Chassis No:	WDD2130042A061017
Colour:	Black	Odometer:	234189 km
Engine Capacity:	1950 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	KAPSEN 5 mm	Rear Left Side:	KAPSEN 5 mm
Front Right Side:	KAPSEN 5 mm	Rear Right Side:	KAPSEN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,575.23	5,968.16	13,607.07	69.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,240.00	1,860.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,675.23	7,208.16	15,467.07	68.21
Approved Total (Overridden) (S\$)		5,750.00		

(S\$)	22,675.23	5,750.00	16,925.23	74.64
+ GST 7.00/7.00% (S\$)	1,587.27	402.50	1,184.77	74.64
Nett Amount (S\$)	24,262.50	6,152.50	18,110.00	74.64
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
Nett Liability (S\$)		7,052.50		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 27/11/2020

Date Inspected: 30/11/2020

Estimated Period of Repair: 4.0 days

Inspected At:

160 SIN MING DRIVE #01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,482.60 FL	*1,210.00 FL
2	1		*BONNET INSULATOR	Not Damaged	361.50 FL	*- FL
3	2		*BONNET LOCK ASSY	Not Damaged	517.20 FL	*- FL
4	1		*BONNET LOGO	Necessary	108.50 FL	*108.50 FL
5	1		*FRONT BUMPER	Cracked	1,998.60 FL	*1,200.00 FL
6	2		*FRONT BUMPER TOP BRACKET	Broken (1 PCS ONLY)	796.60 FL	*398.30 FL
7	1		*FRONT BUMPER TOP RUBBER	Not Necessary	168.00 FL	*- FL
8	1		*FRONT BUMPER GRILLE	Broken	1,882.60 FL	*358.00 FL
9	1		*FRONT BUMPER GRILLE LOGO	Not Damaged	250.00 FL	*- FL
10	1		*FRONT BUMPER GRILLE BASE	Not Damaged	652.10 FL	*- FL
11	1		*FRONT BUMPER INNER SPONGE	Broken	234.80 FL	*234.80 FL
12	2		*FRONT BUMPER SIDE RETAINER	Necessary	197.20 FL	*197.20 FL
13	1		*FRONT BUMPER OUTER CHROME GARNISH (3 PCS)	Broken	1,156.80 FL	*385.60 FL
14	2		*FRONT BUMPER PARKING SENSOR	No such part	620.90 FL	*- FL
15	1		*FRONT BUMPER LICENSE PLATE	Not Damaged	143.42 FL	*- FL
16	1		*FRONT SUPPORT PANEL	Not Damaged	1,682.30 FL	*- FL
17	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Damaged	451.20 FL	*- FL
18	1		*HEADLAMP	O/S Broken	5,220.40 FL	*2,450.00 FL
19	2		*HEADLAMP LOWER BRACKET	No such part	751.20 FL	*- FL
20	2		*HEADLAMP PANEL	Not Damaged	1,021.00 FL	*- FL
21	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
22	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*BONNET INSULATOR CLIPS	Not Necessary	60.00 FS	*- FS
24	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
25	6		*FRONT BUMPER PARKING SENSOR SEAL	Not Necessary	348.00 FS	*- FS
26	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	60.00 FS	*- FS
27	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
28	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
29	1		*FRONT NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,644.92	6,622.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,069.69	654.24
Total Parts (\$\$)	19,575.23	5,968.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R FRONT BUMPER PARKING SENSOR	New	150.00	60.00
2	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
3	CHECK WIRING	New	150.00	60.00
4	UPHOLSTERY	New	300.00	0.00
5	PANEL BEAT	New	1,000.00	600.00
6	RUST PROOFING	New	200.00	0.00
7	SPRAY PAINTING	New	1,000.00	400.00
Gross Labour Cost (S\$)			3,100.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >