

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013123/UQD3Q2

Date: 05/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00174682000
Claimant Vehicle No :	SJT5247Z	Insured Vehicle No :	SKT8993X
Date of Loss:	25/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204602/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT5247Z	Engine No:	L13A4245176
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61223170
Reg. Date:	16/10/2009 (Man. Year: 2009)	Odometer:	138106 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Linglong 6 mm	Rear Left Side:	Linglong 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,306.31	3,734.48	5,571.83	59.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	2,620.00	1,840.00	41.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,766.31	6,354.48	7,411.83	53.84
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	13,766.31	5,000.00	8,766.31	63.68
+ GST 7.00/7.00% (S\$)	963.64	350.00	613.64	63.68
Nett Amount (S\$)	14,729.95	5,350.00	9,379.95	63.68

INSPECTION

Date of Assignment:	30/11/2020	
Date Inspected:	30/11/2020 Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	7.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2021)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT5247Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	670.00 FL	*493.70 FL
2	1		*REAR BUMPER DAMPER	O/s Dented	381.50 FL	*105.00 FL
3	2		*REAR BUMPER RETAINER	Bent	60.00 FL	*44.00 FL
4	1		*END PANEL	Badly Dented	775.00 FL	*269.80 FL
5	1		*END PANEL TOP GARNISH	Twisted	187.80 FL	*60.80 FL
6	2		*REAR TAILLAMP	Cracked	635.50 FL	*635.50 FL
7	2		*REAR TAILLAMP PANEL	Repair	348.20 FL	*- FL
8	1		*REAR EXHAUST SILENCER	Repair	546.80 FL	*- FL
9	2		*REAR EXHAUST MOUNTING	Not Necessary	91.50 FL	*- FL
10	1		*REAR FENDER INNER TRIM	Os Distorted/Ns Not Necessary	684.80 FL	*246.20 FL
11	2		*REAR FENDER	Repair	1,608.40 FL	*- FL
12	1		*TAILGATE	Badly Dented	1,050.80 FL	*718.20 FL
13	2		*TAILGATE ABSORBER	Not Necessary	301.30 FL	*- FL
14	1		*TAILGATE EMBLEM-FIT	Bent	41.00 FL	*32.90 FL
15	1		*TAILGATE EMBLEM-HONDA	Necessary	51.20 FL	*35.00 FL
16	1		*TAILGATE OUTER HANDLE	Not Necessary	136.10 FL	*- FL
17	1		*TAILGATE WEATHERSTRIP	Twisted	152.60 FL	*92.30 FL
18	1		*SET TAILGATE GLASS MOULDING	Necessary	282.00 FL	*60.80 FL
19	1		*TAILGATE LOCK	Dented/Shorted	296.30 FL	*145.50 FL
20	1		*TAILGATE LOCK STRIKER	Not Necessary	45.91 FL	*- FL
21	2		*TAILGATE HINGE	Not Necessary	80.50 FL	*- FL
22	1		*TAILGATE INNER TRIM	Deformed/Cracked	316.15 FL	*184.20 FL
23	1		*SPARE TYRE TOP BOARD	Serviceable	323.15 FL	*- FL
24	1		*SPARE TYRE INNER TOOL FOAM	Torn	218.80 FL	*218.80 FL
25	1		*SPARE TYRE COMPARTMENT	Crumpled/Buckled	947.58 FL	*837.90 FL
26	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
27	1		*SET REAR TAILGATE INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
28	1		*SET FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
29	1		*SET END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
30	1		*SET REAR REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
31	1		*NUMBER PLATE	Bent	80.00 FS	*40.00 FS
32	1		*JOINT SEALANT	Necessary	150.00 FS	*50.00 FS
33	1		*FLOOR INSULATOR	Not fitted	150.00 FS	*- FS
34	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,352.89 4,570.60
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,046.58 836.12

Total Parts (\$\$) 9,306.31 3,734.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR LINING,TRIM AND GARNISH	New	200.00	80.00
2	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	50.00
4	REMOVE AND REFIT FUEL TANK	New	200.00	0.00
5	REMOVE AND RENEW FLOOR INSULATOR	New	150.00	0.00
6	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
7	REMOVE AND REFIT EXHAUST SILENCER	New	200.00	60.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	1,100.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,100.00
10	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	80.00
Gross Labour Cost (\$\$)			4,460.00	2,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >