

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20013127/T1VF3E2**Date:** 05/07/2021**REFERENCE**

Insured/Claimant:	MONIQUE GOH	Policy No:	2100273092	
Date of Loss:	21/11/2020	Nature of Claim:	OD	Claim No: 3639813202SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJB118R</b>		
Make & Model:	AUDI S3, 2.0 TFSI Quattro (M)	Engine No:	CDL040855
Reg. Date:	10/01/2011 (Man. Year: 2010)	Chassis No:	WAUZZZ8P0BA072264
Colour:	Silver	Odometer:	218871 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$77,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	27,785.00	16,388.96	11,396.04	41.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,694.00	7,969.00	4,725.00	37.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>40,479.00</b>	<b>24,357.96</b>	<b>16,121.04</b>	<b>39.83</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>23,000.00</b>		
<b>- Excess (\$\$)</b>	2,000.00	2,000.00	0.00	0.00
<b>(\$\$)</b>	38,479.00	21,000.00	17,479.00	45.42
<b>+ GST 7.00/7.00% (\$\$)</b>	2,693.53	1,470.00	1,223.53	45.42
<b>Nett Amount (\$\$)</b>	<b>41,172.53</b>	<b>22,470.00</b>	<b>18,702.53</b>	<b>45.42</b>

**INSPECTION**

Date of Assignment:	30/11/2020		
Date Inspected:	27/11/2020	Inspected At:	24 BENOI SECTOR Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	16.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,467.00 FS	*1,973.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	179.00 FS	*- FS
3	1		*FRONT BUMPER CARRIER	Bent	663.00 FS	*530.00 FS
4	2		*FRONT BUMPER SHOCK ABSORBER - LH / RH	Deformed	432.00 FS	*172.80 FS
5	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	76.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER - LOWER CENTRE	Deformed	379.00 FS	*303.20 FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	192.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	128.00 FS	*102.00 FS
9	1		*WEBBING	Necessary	13.00 FS	*9.68 FS
10	1		*PLASTIC ADHESIVE	Necessary	55.00 FS	*44.00 FS
11	1		*PLASTIC MATERIAL BONDING AGENT	Necessary	57.00 FS	*45.36 FS
12	1		*PLASTIC CLEANER	Necessary	32.00 FS	*25.52 FS
13	1		*RADIATOR GRILLE	Cracked	2,122.00 FS	*1,840.00 FS
14	1		*S3 INSCRIPTION	Necessary	122.00 FS	*97.60 FS
15	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Deformed	650.00 FS	*260.00 FS
16	2		*SIGNAL HORN - LOW / HIGH TONE	Not Necessary	446.00 FS	*- FS
17	1		*SPRING SHACKLE	Not Necessary	66.00 FS	*- FS
18	1		*FRONT FENDER - LH	Repair	750.00 FS	*- FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	48.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - REAR	Not Necessary	49.00 FS	*- FS
21	1		*FRONT FENDER BRACKET - CENTRE	Not Necessary	49.00 FS	*- FS
22	1		*FRONT FENDER BRACKET - FRONT	Not Necessary	49.00 FS	*- FS
23	1		*FRONT FENDER BRACE - LH	Not Necessary	53.00 FS	*- FS
24	1		*WHEEL HOUSING LINER - OUTER	Not Necessary	167.00 FS	*- FS
25	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
26	1		*WHEEL HOUSING LINER - OUTER	Not Necessary	167.00 FS	*- FS
27	1		*WHEEL HOUSING LINER - INNER	Not Necessary	128.00 FS	*- FS
28	1		*WHEEL HOUSING LINER - INNER	Not Necessary	128.00 FS	*- FS
29	2		*WHEEL SPOILER - LH / RH	Not Necessary	112.00 FS	*- FS
30	1		*BONNET	Bent	2,373.00 FS	*1,898.40 FS
31	1		*BONNET ATTACHMENT PARTS	Not Necessary	96.00 FS	*- FS
32	2		*BONNET LID HINGE - LH / RH	Not Necessary	114.00 FS	*- FS
33	1		*BONNET CATCH HOOK	Not Necessary	92.00 FS	*- FS
34	1		*BONNET LID LOCK	Not Necessary	212.00 FS	*- FS
35	1		*LID LOCK MICRO SWITCH	Not Necessary	110.00 FS	*- FS
36	1		*BONNET LOCK COVER - UPPER FRONT	Deformed	51.00 FS	*40.16 FS
37	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	234.00 FS	*187.20 FS
38	2		*HEADLIGHT - LH / RH	Cracked	4,006.00 FS	*3,204.80 FS
39	2		*LIFT CYLINDER - LH / RH	Not Necessary	402.00 FS	*- FS
40	5		*LIFT CYLINDER HOSE	Not Necessary	184.00 FS	*- FS
41	1		*LOCK CARRIER	Cracked	971.00 FS	*776.80 FS
42	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	58.00 FS	*- FS
43	1		*READY MIX COOLANT	Necessary	91.00 FS	*72.32 FS
44	1		*AIRCON CONDENSER	Bent	515.00 FS	*411.60 FS
45	2		*RADIATOR AIR GUIDE - LH / RH	Deformed	78.00 FS	*61.76 FS
46	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
47	1		*AIRCON STICKER	Necessary	18.00 FS	*13.84 FS
48	1		*REAR BUMPER	Deformed	2,300.00 FS	*1,840.00 FS
49	1		*REAR BUMPER FIXING PARTS	Not Necessary	132.00 FS	*- FS
50	1		*REAR BUMPER SPOILER - LOWER CENTRE	Not Necessary	1,177.00 FS	*- FS
51	1		*REAR BUMPER COVER - UPPER	Not Necessary	59.00 FS	*- FS
52	1		*REAR REINFORCEMENT BEAM	Not Necessary	620.00 FS	*- FS
53	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	26.00 FS	*- FS
54	2		*REAR BUMPER GUIDE SECTION - LH / RH INNER	Not Necessary	132.00 FS	*- FS
55	2		*REAR PARKING AID SENSOR	Not Necessary	500.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
57	1		*SUNDRIES	Necessary	400.00 FS	*81.12 FS
58	1		*FRONT AIR GUIDE (Supplementary)	Cracked	83.00 FS	*66.00 FS
59	1		*ADDITIONAL RADIATOR (Supplementary)	Bent	1,064.00 FS	*851.20 FS
60	1		*RADIATOR (Supplementary)	Bent	1,263.00 FS	*1,010.40 FS
61	1		*FRONT CONNECTING PIPER - RIGHT LOWER (Supplementary)	Necessary	341.00 FS	*272.40 FS
62	1		*FRONT PRESSURE HOSE - LH LOWER (Supplementary)	Necessary	158.00 FS	*126.40 FS
F=Franchise part. S=SpcNett.						
				<b>Total Parts (S\$)</b>	<b>27,785.00</b>	<b>16,388.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES	New	700.00	500.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	2,625.00
5	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER	New	3,000.00	1,650.00
6	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
7	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
8	TO RESPRAY REAR BUMPER	New	900.00	550.00
9	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK	New	384.00	384.00
<b>Gross Labour Cost (\$\$)</b>			<b>12,694.00</b>	<b>7,969.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >