

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20013128/EQF3E2

Date: 02/02/2021

REFERENCE

Insured/Claimant:	ZOLPAKAR BIN ABDUL KARIM	Policy No:	2070106804	
Date of Loss:	25/11/2020	Nature of Claim:	OD	Claim No: 1846588350SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT7826D	Engine No:	G4FGKH755670
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416ML5069521
Reg. Date:	17/07/2020 (Man. Year: 2019)	Odometer:	5173 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,957.40	10,635.40	1,322.00	11.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,690.00	7,510.00	1,180.00	13.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,647.40	18,145.40	2,502.00	12.12
+ GST 7.00/7.00% (S\$)	1,445.32	1,270.18	175.14	12.12
Nett Amount (S\$)	22,092.72	19,415.58	2,677.14	12.12

INSPECTION

Date of Assignment:	30/11/2020	
Date Inspected:	30/11/2020	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	15.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD,LH	Broken	1,219.00 FL	*1,219.00 FL
2	1		*KNUCKLE-FRONT AXLE,LH	Bent	350.00 FL	*350.00 FL
3	1		*HUB ASSY-FR WHEEL	Necessary	436.00 FL	*436.00 FL
4	1		*KNUCKLE-FRONT AXLE,LH	Not Necessary	350.00 FL	*- FL
5	1		*GEAR ASSY-STEERING	Bent	770.00 FL	*770.00 FL
6	1		*LINK-STABILIZER	Bent	72.00 FL	*72.00 FL
7	1		*BAR ASSY-FR STABILIZER	Not Necessary	238.00 FL	*- FL
8	1		*STRUT ASSY-FR,LH	Bent	280.00 FL	*280.00 FL
9	1		*INSULATOR ASSY-STRUT	Necessary	85.00 FL	*85.00 FL
10	1		*BEARING-STRUT	Necessary	86.00 FL	*86.00 FL
11	1		*PAD-FRONT SPRING,LWR	Necessary	23.00 FL	*23.00 FL
12	1		*CROSSMEMBER COMPL	Bent	1,156.00 FL	*1,156.00 FL
13	1		*ARM COMPLETE-FR LWR,LH	Bent	286.00 FL	*286.00 FL
14	1		*STAY LH	Not Necessary	22.00 FL	*- FL
15	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
16	1		*HINGE ASSY-HOOD,RH	Not Necessary	43.00 FL	*- FL
17	1		*HINGE ASSY-HOOD,LH	Not Necessary	43.00 FL	*- FL
18	1		*PANEL-FENDER,LH	Dented	430.00 FL	*430.00 FL
19	1		*INSULATOR-FENDER,LH	Crushed	27.00 FL	*27.00 FL
20	1		*PANEL ASSY-FRONT DOOR,LH	Dented	1,277.00 FL	*1,277.00 FL
21	1		*HINGE ASSY-FRONT DOOR,LH	Not Necessary	30.00 FL	*- FL
22	1		*HINGE ASSY-DOOR LOWER,LH	Not Necessary	27.00 FL	*- FL
23	1		*PANEL ASSY-REAR DOOR,LH	Dented	1,377.00 FL	*1,377.00 FL
24	1		*HINGE ASSY-REAR DOOR UPPER,LH	Not Necessary	33.00 FL	*- FL
25	1		*HINGE ASSY-DOOR UPPER,LH	Not Necessary	26.00 FL	*- FL
26	1		*PAD-HOOD INSULATING	Not Necessary	156.00 FL	*- FL
27	1		*MOULDING ASSY-FRT DR FRAME,LH	Necessary	37.00 FL	*37.00 FL
28	1		*W/STRIP ASSY-FR DR BELT O/S LH	Not Necessary	64.00 FL	*- FL
29	1		*W/STRIP ASSY-FR DR SIDE LH	Not Necessary	102.00 FL	*- FL
30	1		*W/STRIP-FR DR BELT I/S LH	Not Necessary	43.00 FL	*- FL
31	1		*MOULDING ASSY-RR DR FRAME,LH	Necessary	44.00 FL	*44.00 FL
32	1		*W/STRIP ASSY-RR DR BELT O/S LH	Not Necessary	60.00 FL	*- FL
33	1		*W/STRIP ASSY-RR DR SIDE LH	Not Necessary	102.00 FL	*- FL
34	1		*BLACK TAPE-FR DR RR,LH	Necessary	13.00 FL	*13.00 FL
35	1		*BLACK TAPE-RR DR FR,LH	Necessary	13.00 FL	*13.00 FL
36	1		*BLACK TAPE-RR DR FRAME RR OTR	Necessary	8.00 FL	*8.00 FL
37	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
38	1		*GUARD ASSY-FRONT WHEEL,LH	Crushed	95.00 FL	*95.00 FL
39	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
40	1		*GRILLE-FRONT BUMPER	Not Necessary	262.00 FL	*- FL
41	1		*AIR DUCT-FR BUMPER,LH	Not Necessary	14.00 FL	*- FL
42	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 FL	*22.00 FL
43	1		*NEW K3 2020 BODYKIT	Broken	1,721.00 FS	*1,721.00 FS
44	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
45	1		*HOSE-BRAKE FRONT LH	Bent	58.00 FL	*58.00 FL
46	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
47	1		*CLIP	Necessary	4.00 FL	*4.00 FL
48	1		*FILM-ANTI CHIPPG LH	Necessary	27.00 FL	*27.00 FL
49	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
50	1		*TUBE-H/MODULE TO FR LH	Bent	42.00 FL	*42.00 FL
51	1		*LOWER COVER-U/H J/BOX	Broken	13.00 FL	*13.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					14,504.00	12,859.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					2,546.60	2,223.60
Total Parts (\$\$)					11,957.40	10,635.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,FRT LH FENDER,FRT LH DOOR,REAR LH DOOR,BONNET & AFFECTED AREA.REPAIR ON REAR LH FENDER & LH ROCKER PANEL	New	3,200.00	2,400.00
2	PAINT WORK ON FRT BUMPER,BONNET,FRT LH FENDER,FRT LH DOOR,REAR LH DOOR,REAR LH FENDER & LH ROCKER PANEL	New	2,450.00	2,450.00
3	TRANSFER FRONT LH DOOR ATTACHMENT TO NEW PANEL	New	120.00	120.00
4	TRANSFER REAR LH DOOR ATTACHMENT TO NEW PANEL	New	120.00	120.00
5	PERFORM RUST PREVENTION	New	40.00	40.00
6	TO SUPPLY FRONT LH SPORT RIM	New	480.00	480.00
7	TO SUPPLY FRONT LH WHEEL TYRE	New	380.00	300.00
8	REPLACE FRONT UNDERCARRIAGE	New	400.00	400.00
9	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
12	TO TRANSFER FRT LH RIM INCLUDING BALANCING	New	30.00	30.00
13	REMOVE & INSTALL LH SIDE SKIRTING & AIR DAM	New	400.00	100.00
14	REPAIR ON LH WHEEL HOUSING AREAS & REPLACE FRONT SUPPORT PANEL	New	600.00	600.00
15	REMOVE & REINSTALL A/COND CONDENSER & RADIATOR ASSY TO FACILITATE REPAIR	New	120.00	120.00
16	VACUUM & TOP UP A/COND GAS	New	80.00	80.00
Gross Labour Cost (\$\$)			8,690.00	7,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >