

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. Q 3C**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER FASCIA (WCP)	DISTORTED / TORN	720.00	715.00
1	SET FRONT BUMPER CLIPS (WCP)	NECESSARY	60.00	42.00
1	FRONT BUMPER SIDE RETAINER LH (WCP)	NOT NECESSARY	9.00	-
1	FRONT BUMPER LOWER COVER LH (WCP)	NOT NECESSARY	26.00	-
2	FRONT BUMPER PARKING SENSOR LH @\$90.00 (WCP)	NOT NECESSARY	180.00	-
1	HEADLAMP ASSY LH (WCP)	SCRATCHED / CRACKED	2,350.00	2,300.00
1	HEADLAMP LOWER BRACKET LH (WCP)	NOT NECESSARY	140.00	-
1	FRONT FENDER LH (WCP)	TO REPAIR SEE LABOUR	430.00	-
1	WIPER TANK (WCP) (ADDITIONAL)	TORN	90.00	90.00
	COST PLUS 10%		400.50	314.70
			4,405.50	3,461.70
	<b><u>LABOUR</u></b>			
	CUT OUT, RENEW, KNOCKING & WELDING FRONT BUMPER FASCIA, FRONT FENDER LH, FRONT BUMPER SIDE BRACKET, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY. INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		680.00	300.00
	SPRAY PAINTING ON DAMAGE PARTS.		600.00	500.00
	REMOVE & REFIX FRONT BUMPER SENSOR.		80.00	40.00
	CHECK ALL LIGHTING AFTER REPAIRS.		65.00	20.00
	DIAGNOSTIC RESET AFTER REPAIRS.		280.00	60.00
			1,705.00	920.00
	<b>GRAND TOTAL</b>		<b>6,110.50</b>	<b>4,381.70</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,381.70</b>

Report Ref No. CS/LPC20013130/Usf3e2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.