

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20013131/T1QF3E2

Date: 04/02/2021

REFERENCE

Insured/Claimant: SOUTH AIR-COND &
REFRIGERATION PTE LTD

Policy No: DMCVSNW00107222000

Date of Loss: 23/11/2020

Nature of
Claim: OD

Claim
No: SNM20D204567/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK7247C**

Make & Model: NISSAN NV350, 2.5 D Panel Van (M)

Engine No: YD25081023B

Reg. Date: 31/10/2020 (Man. Year: 2020)

Chassis No: JN1MC2E26Z0032430

Colour: Grey

Odometer: 1892 km

Engine Capacity: 2488 cc

Market Value/New Car Price: S\$68,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,660.48	3,410.80	249.68	6.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,788.00	1,978.00	810.00	29.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,448.48	5,388.80	1,059.68	16.43
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	5,948.48	4,888.80	1,059.68	17.81
+ GST 7.00/7.00% (S\$)	416.39	342.22	74.17	17.81
Nett Amount (S\$)	6,364.87	5,231.02	1,133.85	17.81

INSPECTION

Date of Assignment: 30/11/2020

Date Inspected: 30/11/2020 Inspected At:

Tan Chong Motor Sales Pte Ltd (Bukit Timah)
911, Bukit Timah Road
Singapore 589622

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Feb 2021)	
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK7247C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE-RR BUMPER	Deformed	667.20 FN	*667.20 FN
2	10		*CLIP	Necessary	13.00 FN	*13.00 FN
3	1		*BRKT-RR BMPR	Bent	171.90 FN	*171.90 FN
4	1		*DOOR BACK	Bent	1,816.70 FN	*1,816.70 FN
5	1		*SEALANT -W/SCREEN GLASS	Necessary	80.00 FS	*80.00 FS
6	1		*RUBBER-DUM	Necessary	63.80 FN	*63.80 FN
7	1		*GLASS-TAIL GATE	Necessary	891.00 FN	*891.00 FN
8	1		*LOCK & REMOCON	Not Necessary	287.10 FN	*- FN
9	1		*EMBLEM-REAR	Necessary	64.90 FN	*64.90 FN
10	1		*EMBLEM-BACK DOO	Necessary	110.00 FN	*110.00 FN
11	1		*SENSOR-REVERSE	Not Working	250.00 FS	*250.00 FS
12	1		*LABEL 70KM/H	Necessary	10.00 FS	*10.00 FS
13	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
14	1		*LABEL-8PAX	Necessary	12.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	4,477.60	4,170.50
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	817.12	759.70
Total Parts (\$\$)	3,660.48	3,410.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	New	120.00	0.00
2	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	New	240.00	120.00
3	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	New	55.00	55.00
4	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	100.00	100.00
5	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	New	150.00	0.00
6	CHECK LIGHTING	New	48.00	48.00
7	TRANSFER MECHANISM PART FOR TAILGATE	New	80.00	80.00
8	RENEW RR WINDSCREEN	New	250.00	250.00
9	REPAIR RR END PANEL & RENEW RR BUMPER TAILGATE & RR END PANEL OUTER	New	1,120.00	700.00
10	S/PAINT RR BUMPER, TAILGATE (1.5) & RR END PANEL	New	625.00	625.00
Gross Labour Cost (\$\$)			2,788.00	1,978.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >