

A.S.S. REC. BY: TaufikhREF: 09/CT12001317/T19f3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. DMCVSNW00107222000Claims No. SNM20D204567


Sum Insured: _____

Excess: \$500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 68K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRSDate: _____ Person Contacted: Zuhri

Vehicle: IN / OUT

Veh No: G BK7247CYr Regn: 2018 Apr 1Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan NV350c.c. 2488Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 1892

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SNMCTE26.20032430

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/R15R: 2BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at Tan Chong Bhat timeDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 30/11/2020

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

02/12/20 @ 4.07pm revert to Jenny Lew via Merimen.

03/12/20 @ 10.26am Adeline Chng informed C/A via Merimen.

03/12/20 @ 12.08pm Informed Zuhri C/A & ex: \$500 by email.

13/01/21 @ 12.32pm Taufikh finalised with Zuhri final fig \$5388.80, 5 days (Red \$1059.68, 16%)

Date/Time, File Pass to?

☐ : Prell. Report

22/01 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Form: MER-ODLump Sum / F.B.I. / 5388.80

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0296/2020
DATE : 26-NOV-2020

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

Od Recovery Claim / 30.11.20
Waiting 10.00 AM -
11.00 AM

OWNER'S NAME : M/S SOUTH AIR-COND & REFRIGERATION PTE. LTD.
ADDRESS : BLK 2022 BUKIT BATOK ST 23
#02-164
S(659527)
TELEPHONE NO : 65600800

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DMCVSNW00107222000
VEHICLE NO : GBK7247C
MODEL CODE : MVL2RDRE26KW3JBT-E
MODEL/YEAR : NISSAN NV350 PANEL VAN 5DR 2.5 SMT MY2019
ENGINE NO : YD25081023B
CHASSIS NO : JN1MC2E26Z0032430
MILEAGE : 1 KM
DATE IN : 26/11/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 23/11/2020

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBK7247C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	X
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	120.
3 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	✓
5 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	X
6 ZZ/001	CHECK LIGHTING	48.00	✓
7 ZZ/002	TRANSFER MECHANISM PART FOR TAILGATE	80.00	✓
8 ZZ/003	RENEW RR WINDSCREEN	250.00	✓
9 ZZ/004	REPAIR RR END PANEL & RENEW RR BUMPER TAILGATE & RR END PANEL OUTER	1120.00	780.
10 ZZ/005	S/PAINT RR BUMPER ,TAILGATE(1.5) & RR END PANEL	625.00	250. 6
TOTAL LABOUR CHARGES		2788.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBK7247C

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 FACE-RR BUMPER	85022-3XA0A	667.20	del ✓	
2 CLIP(1.3X10)	01553-05933	13.00	nei ✓	
3 BRKT-RR BMFR	85040-V200A	171.90	?	
4 DOOR BACK	K010M-3XBFA	1816.70	bt ✓	
5 SEALANT - W/SCREEN GLASS	SEALANT - 2			80.00 nei ✓
6 RUBBER-DUM	G2G16-89900	63.80	nei ✓	
7 GLASS-TAIL GATE	90300-3XA0A	891.00	? photo	
8 LOCK & REMOCON	90500-5YE0A	287.10	?	
9 EMBLEM-REAR	90890-JX00A	64.90	nei ✓	
10 EMBLEM-BACK DOO	90890-3XY0A	110.00	nei ✓	
11 SENSOR-REVERSE	SENSOR			250.00 nw ✓
12 LABEL 70KM/H	SWD-70KM			10.00 nei ✓
13 LABEL-8PAX	PAX-8			12.00 nei ✓
14 SUNDRIES	NPN			40.00 20.
SUB TOTAL		4085.60	0.00	392.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		817.12	0.00	0.00
GRAND TOTAL		3268.48	0.00	392.00
OVERALL TOTAL		3660.48		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBK7247C

TOTAL LABOUR CHARGES	2788.00
TOTAL SPARE PARTS CHARGES	3660.48
GRAND TOTAL	6448.48 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Tanji 97495744/67418434
Not Authorized 30/11/20 2245pm
Ex: \$500
Resurvey before paint
05 days
tanji@lkkauto.com

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: