

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBK7247C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	X 111
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	120.
3 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	✓
5 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	X 111
6 ZZ/001	CHECK LIGHTING	48.00	✓
7 ZZ/002	TRANSFER MECHANISM PART FOR TAILGATE	80.00	✓
8 ZZ/003	RENEW RR WINDSCREEN	250.00	✓
9 ZZ/004	REPAIR RR END PANEL & RENEW RR BUMPER TAILGATE & RR END PANEL OUTER	1120.00	280 700.
10 ZZ/005	S/PAINT RR BUMPER ,TAILGATE(1.5) & RR END PANEL	625.00	250. ✓ 1978
TOTAL LABOUR CHARGES		2788.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBK7247C

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1 FACE-RR BUMPER	85022-3XA0A	667.20	del ✓		
2 CLIP(1.3X10)	01553-05933	13.00	nei ✓		
3 BRKT-RR BMPR	85040-VZ00A	171.90	? bt ✓		
4 DOOR BACK	K010M-3XBFA	1816.70	bt ✓		
5 SEALANT - W/SCREEN GLASS	SEALANT - 2			80.00	nei ✓
6 RUBBER-DUM	G2G16-89900	63.80	nei ✓		
7 GLASS-TAIL GATE	90300-3XA0A	891.00	? photo nei ✓		
8 LOCK & REMOCON	90500-5YE0A	287.10	X nei ✓		
9 EMBLEM-REAR	90890-JX00A	64.90	nei ✓		
10 EMBLEM-BACK DOO	90890-3XY0A	110.00	nei ✓		
11 SENSOR-REVERSE	SENSOR			250.00	nei ✓
12 LABEL 70KM/H	SWD-70KM			10.00	nei ✓
13 LABEL-8PAX	PAX-8			12.00	nei ✓
14 SUNDRIES	NPN			40.00	20.

SUB TOTAL

4085.60 0.00 392.00

LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)

817.12 0.00 0.00

GRAND TOTAL

3268.48 0.00 392.00

OVERALL TOTAL

3660.48

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

List 3798.50

20% 3038.80

2N

372

1978

3038.80

372

45388.80

5 days
#