

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013133/AGTF3Q2

Date: 20/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001379027

Claimant
Vehicle No : SLN5981U

Insured Vehicle No : PC3558H

Date of Loss: 26/11/2020

Nature of Claim: TP

Claim No: 250264

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN5981U**

Make & Model: TOYOTA WISH, 1.8 CVT (A)

Engine No: 2ZR1945867

Reg. Date: 11/05/2017 (Man. Year: 2017)

Chassis No: JTDGG20W60J006793

Colour: Grey

Odometer: 113954 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,845.40	3,121.85	3,723.55	54.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,150.00	1,230.00	36.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,225.40	5,271.85	4,953.55	48.44
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	10,225.40	4,200.00	6,025.40	58.93

INSPECTION

Date of Assignment: 30/11/2020

Date Inspected: 30/11/2020 Inspected At:

Hiap Hong Motor Repair (HQ)
2 Kaki Bukit Avenue 2, #02-13 Kaki
Bukit Autohub
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2021)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN5981U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	581.10 F	*581.10 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	116.80 F	*116.80 FL
3	1		*REAR BUMPER IMPACT BRACKET	N/s Dented	137.00 F	*68.50 FL
4	1		*REAR BUMPER REFLECTOR	N/s Cracked	117.80 F	*58.90 FL
5	1		*REAR END PANEL OUTER	Dented	581.40 F	*581.40 FL
6	1		*REAR END PANEL INNER	Repair	199.50 F	*- FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	253.20 F	*253.20 FL
8	1		*TAILGATE	Dented	1,209.40 F	*1,209.40 FL
9	1		*TAILGATE LOCK	Not Necessary	315.70 F	*- FL
10	1		*TAILGATE WEATHERSTRIPE	Cut	299.10 F	*299.10 FL
11	1		*TAILGATE INNER TRIM BOARD	Not Necessary	485.50 F	*- FL
12	1		*TAILGATE LAMP LH	Cracked	277.60 F	*277.60 FL
13	1		*TAILGATE GLASS MOULDING	Necessary	132.40 F	*132.40 FL
14	1		*TOYOTA LOGO	Necessary	70.20 F	*70.20 FL
15	1		*VALVE Matic EMBLEM	Necessary	47.20 F	*47.20 FL
16	1		*TAILLAMP LH	Not Necessary	395.50 F	*- FL
17	1		*FLOOR PANEL TOP BOARD	Not Necessary	456.60 F	*- FL
18	1		*REAR LH FENDER INNER TRIM BOARD	Not Necessary	679.40 F	*- FL
19	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
20	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
21	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
22	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
23	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
24	1		*REAR LH FENDER INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **6,845.40** **4,045.80**
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 923.95

Total Parts (\$\$) **6,845.40** **3,121.85**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO REMOVE REAR CAMERA	New	100.00	60.00
6	TO REMOVE VIDEO RECORDER	New	100.00	60.00
7	TO REMOVE UPHOLSTERY	New	150.00	80.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO SPRAY TUFF COAT	New	150.00	60.00
Gross Labour Cost (\$\$)			3,380.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >